ANN ARBOR HISTORIC DISTRICT COMMISSION

Staff Report

ADDRESS: 1540 Cedar Bend Drive, Application Number HDC16-164

DISTRICT: Broadway Historic District

REPORT DATE: August 11, 2016

REPORT PREPARED BY: Jill Thacher, Historic Preservation Coordinator

REVIEW COMMITTEE DATE: Monday, August 8, 2016

OWNER APPLICANT

Name: Mike and Megan Turriff Terrafirma Inc. - Eric Patterson

Address: 1540 Cedar Bend Dr. 3780 Morgan Rd.

Ann Arbor, MI 48105 Ypsilanti, MI 48197

Phone: (734) 883-1416 (734) 434-3811

BACKGROUND: The Godfrey Ottmar House was constructed in 1930 in the Tudor Revival style. It is clad in brick with stuccoed faux half-timbering, and features a variety of dormers, a front bay window, and a gothic arch at the front entry. See the attached Broadway Historic District Survey for more information.

LOCATION: The site is located on the northeast side of Cedar Bend Drive, south of Broadway.

APPLICATION: The applicant seeks HDC approval to repave the front walkway with pavers, and install a paver driveway on a drive that is currently gravel.

APPLICABLE REGULATIONS

From the Secretary of the Interior's Standards for Rehabilitation:

- (2) The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces, and spatial relationships that characterize a property will be avoided.
- (9) New additions, exterior alterations, or related construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
- (10) New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property will be unimpaired.

From the Secretary of the Interior's Guidelines for Rehabilitating Historic Buildings (other SOI Guidelines may also apply):

Building Site

Recommended: Retaining the historic relationship between buildings, landscape features, and open space.

Identifying, retaining, and preserving buildings and their features as well as features of the site that are important in defining its overall historic character.

Not Recommended: Introducing new construction onto the building site which is visually incompatible in terms of size, scale, design, materials, color and texture or which destroys historic relationships on the site.

Removing or radically changing buildings and their features or site features which are important in defining the overall historic character of the building site so that, as a result, the character is diminished.

From the Ann Arbor Historic District Design Guidelines (other Ann Arbor guidelines may also apply):

Driveways and Paved Areas

Appropriate: Retaining and maintaining historic sidewalks, walkways, driveways, and patios/terraces.

Not appropriate: Installing driveways or parking areas that are too wide or large for the building site and are out of character for the district.

Reconstructing any sidewalk, driveway, terrace, patio, and other landscape features without sufficient documentation of what the historic feature looked like.

Landscape Features

Not Appropriate: Introducing any new building, streetscape, or landscape feature that is out of scale or otherwise inappropriate to the district's historic character.

STAFF FINDINGS

- 1. The driveway is gravel, and the applicant states that shifting gravel and drainage/runoff issues would be resolved by paving. Snow removal is a problem in the winter because of the large size of the gravel on the driveway and the slope of the site is not graded for proper drainage, and the sloped part becomes slippery and difficult to navigate. Unilock pavers are an appropriate surface that won't be mistaken for a historic material. The extent of the pavers matches the current extent of the gravel.
- 2. The applicant states that the stone paver walkway is falling apart and in need of repair. The walkway was not paved in the 1947 aerial photo (see end of staff report), though a path is shown in nearly the same location. Later aerials distinctly show a paved walkway. Since the pavers were installed after 1947, staff is not concerned about retaining the current stone material. Replacing it with Unilock pavers to match the driveway is an

appropriate choice of materials.

- 3. The landscaping shown on the supplied drawing does not have any hardscape features that would trigger the need for HDC review.
- 4. Staff recommends approval of the application. The proposed work is generally compatible in exterior design, arrangement, texture, material and relationship to the rest of the building and the surrounding neighborhood and meets the *Ann Arbor Historic District Guidelines* for driveways and paved areas and landscape features, and *The Secretary of the Interior's Standards for Rehabilitation*, in particular standards 1, 2 and 10, and the guidelines for building site.

POSSIBLE MOTIONS: (Note that the motion supports staff findings and is only a suggestion. The Review Committee, consisting of staff and at least two Commissioners, will meet with the applicant on site and then make a recommendation at the meeting.)

I move that the Commission issue a certificate of appropriateness for the application at 1540 Cedar Bend Drive, a contributing building in the Broadway Historic District, to install a paver driveway and front walk, as proposed. The work is compatible in exterior design, arrangement, texture, material and relationship to the surrounding resources and meets the *Ann Arbor Historic District Guidelines* for driveways and paved areas and landscape features, and *The Secretary of the Interior's Standards for Rehabilitation*, in particular standards 2, 9, and 10, and the guidelines for building site.

MOTION WORKSHEET:

I move that the Commission issue a Certificate of Appropriateness for the work at <u>1540 Cedar Bend Drive</u> in the <u>Broadway</u> Historic District

Provided the following condition(S) is (ARE) met: 1) STATE CONDITION(s)


The work is generally compatible with the size, scale, massing, and materials and meets the Secretary of the Interior's Standards for Rehabilitation, standard(S) number(S) (circle all that apply): 1, 2, 3, 4, 5, 6, 7, 8, 9, 10

ATTACHMENTS: Broadway Historic District Survey, application, photos, drawings, paver details

1540 Cedar Bend Drive (Google Street View, 2014)



1947 Aerial showing unpaved path in approximately the same location



Broadway Historic District

Resource Documentation

Address: 1540 Cedar Bend Date: 1930

Historic Name: Godfrey Ottmar House Level: Contributing



Description

Style: Tudor Revival Roof Shape: Side Gable

Stories: 1.5 Roof Material: Asphalt
Material: Brick Plan Shape: Rectangular
Windows: Original Porch Type: N/A

Windows: Original Porch Type: N/A Window Type: Wood, Double-Hung # Dormers: 2

Pane Type: 4/4, 6/6 Dormer Type: Shed, Segmental

Complex roof with side gable at east, hipped at west and steeply pitched hipped roof over entry pavilion; polygonal bay at west end with tall witch's hat roof; first-story sash = 4/4, upper half-story sash = 6/6 and 4/4; two-window shed dormer to right of entry pavilion, and single-window segmental roof wall dormer breaking eave line to the left; entry pavilion has Gothic arch with narrow multi-light window to the inside left and a wide paneled door to the right; half-timbered upper-story wall is supported by quarter-round brackets;

four-window bay to the right of entry.

History

First City Directory: 1930 Context(s):

Original Use:ResidentialArchitect:UnknownCurrent Use:ResidentialBuilder:Unknown

Occupation (First Dweller): Grocer

Notes: Original owner was Godfrey Ottmar, born in Germany (1865), who ran a grocery store on West Washington. After Mr. Ottmar passed away, Dr. John Bugher, Assistant Professor of Pathology (UM) lived here before moving on to the Rockefeller Foundation in 1937. Otto LaPorte taught Theory of Spectra and Quantum Mechanics in UM's Physics Department and lived here from 1939-40.



City of Ann Arbor PLANNING & DEVELOPMENT SERVICES — PLANNING SERVICES

301 E. Huron Street | P.O. Box 8647 | Ann Arbor, Michigan 48107-8647 p. 734.794.6265 | f. 734.994.8312 | planning@a2gov.org

ANN ARBOR HISTORIC DISTRICT COMMISSION APPLICATION


Section 1: Property Being Reviewed and Ownership Information		
Address of Property: 1540 Cedar Bend Drive Ann Arbor MI 48105		
Historic District: Broadway		
Name of Property Owner (If different than the applicant):		
Mike & Megan Turriff		
Address of Property Owner: 1540 Cedar Bend Drive		
Daytime Phone and E-mail of Property Owner: 734-883-1416 meganturriff@yahoo.com		
Signature of Property Owner:		
Section 2: Applicant Information		
Name of Applicant:Terrafirma Inc Eric Patterson		
Address of Applicant: 3780 Morgan Road Ypsilanti MI 48197		
Daytime Phone: (734) 434-3811 Fax:(734) 434-2830		
E-mail: eric@terrafirmalandscape.net		
Applicant's Relationship to Property:owner _x architect _x contactorother		
Signature of applicant: Date:		
Section 3: Building Use (check all that apply)		
χ_ Residentialx_ Single Family Multiple Family Rental		
Commercial Institutional		
Section 4: Stille-DeRossett-Hale Single State Construction Code Act (This item MUST BE INITIALED for your application to be PROCESSED)		
Public Act 169, Michigan's Local Historic Districts Act, was amended April 2004 to include the following language: "the applicant has certified in the application that the property where the work will be undertaken has, or will have before the proposed completion date, a a fire alarm or smoke alarm complying with the requirements of the Stille-DeRossett-Hale Single State Construction Code Act, 1972 PA 230, MCL 125.1501 to 125.1531."		
Please initial here:		

Section 5: Description of Proposed Changes (attack	n additional sheets as necessary)	
Provide a brief summary of proposed changes.		
Re-landscaping front of home, new paver walkway & paver driveway tastefully designed by registered		
architects to period correct architecture.		
2. Provide a description of existing conditions		
Existing landscaping overgrown and many dead plan	ts. Front walkway is falling apart. Gravel driveway	
is weedy and not graded for proper drainage.		

3. What are the reasons for the proposed changes	5?	
To improve aesthetics of home and make landscape	architecturally correct to the "period" of the home.	
The walkway needs to be replaced so it is safe to na	vigate. The driveway needs to be re-built to	
eliminate standing water and dangerous winter ice be	uild up.	
Attach any additional information that will furthe these attachments here.	r explain or clarify the proposal, and indicate	
Attach photographs of the existing property, inc photos of proposed work area.	luding at least one general photo and detailed	
STAFF USI	<u>E ONLY</u>	
Date Submitted:	Application toStaff orHDC	
Project No.: HDC	Fee Paid:	
Pre-filing Staff Reviewer & Date:	Date of Public Hearing:	
Application Filing Date:	Action:HDC COAHDC Denial	
Staff signature:	HDC NTPStaff COA	
Comments:		









Colors











Brussel Block Pavers Unilock

Shapes & Sizes




XL Stone 34.8 cm x 20.8 cm x 7 cm 13.75" x 8.25" x 2.75"



Standard Stone 20.8 cm × 17.3 cm × 7 cm 8.25" × 6.75" × 2.75"



Half Stone 17.8 cm x 10.4 cm x 7 cm 7" x 4" x 2.75"



Brussels Block AF

Half Stone (20%) Standard (40%) XL (40%)

Downloads

Pattern Sheet (.pdf)

.PAT (Imperial)

.PAT (Metric)