

Ann Arbor Crash Review Team Report

July 2025

Location: Miller Ave at Red Oak

Crash Summary

<i>(Location, Date/Time, Involved Units/Parties, Roadway Conditions, Weather Conditions, Contributing Factors, Criminal Responsibility)</i>

UD-10 Number: Unavailable at time of review

Date/Time: 6/19/2025, 2:32 p.m.

Number of Involved Units/Parties: 1

Roadway Conditions: Closed construction site, unpaved surface

Weather Conditions: Clear, Dry

Lighting Conditions: Daylight

Contributing Factors/Description:

Gravel Hauler in closed construction zone dumping a load of gravel with truck in skewed position. As dump bed elevated the soil under one side of the trailer loosened and caused trailer to tip sideways. The trailer rotated onto the truck cab resulting in the cab being crushed.

Dangerous Behaviors

Speed	Failure to Yield	Impaired Driving	Disregard Traffic Control	Reckless / Careless Driving

Other Behaviors of Note:

- Driver – Vehicle trailer was raised in a dangerous position.

Enforcement Response

Concerns Identified	None
Near-Term Strategies (0-90 Days)	
Mid-Term Strategies (90-365 days)	
Long-Term Strategies (1 year +)	

Engineering/Planning Response

Concerns Identified	None
Near-Term Strategies (0-3 years)	
Mid-Term Strategies (4-10 years)	
Long-Term Strategies (11-20 years)	

Education Response:

Concerns Identified	Construction Site Safety
Near-Term Strategies	<ul style="list-style-type: none">• City Safety team are developing a communication that will be sent out to all contractors with active construction projects in the city.• Work was stopped after the incident. Contractor, Engineering, & Safety representatives reviewed the incident on-site and determined what actions the contractor would take in response to the incident.• MIOSHA conducted an incident investigation starting on 6/20/2025
Mid-Term Strategies	
Long-Term Strategies	

90 Day Update

--

One Year Update

--