ANN ARBOR HISTORIC DISTRICT COMMISSION

Staff Report

217 Third Street, Application Number HDC16-282 ADDRESS:

DISTRICT: Old West Side Historic District

REPORT DATE: December 8, 2016

REPORT PREPARED BY: Jill Thacher, Historic Preservation Coordinator

REVIEW COMMITTEE DATE: Monday, December 5, 2016

> OWNER APPLICANT

Name: Martha MacKenzie Same

Address: 1105 Chestnut St

Ann Arbor, MI

(734) 323-2012 Phone:

BACKGROUND: Per Polk City Directories, this two-story gable fronter was first occupied in 1904 by John Seyfried, plumber. Seyfrieds occupied the house until at least 1930. The house features wood lap siding with fishscale shingles in the front gable, a decorative lintel over the front gable's double window, full width front porch with round columns, and wide board trim beneath the eaves.

LOCATION: The site is located on the east side of Third Street, north of Krause and West Liberty and south of West Washington. It backs up to the former road commission building at 415 West Washington.

APPLICATION: The applicant seeks HDC approval to install two shed dormers on the rear wing of the house, remove the chimney, on the south elevation remove a non-original window in an enlarged opening and patch the opening with siding and enlarge another window opening that contains a non-original window, add a new window in a new opening on the rear elevation,


replace a non-original back door, and add a ramp along the

south side of the house to the back deck.

APPLICABLE REGULATIONS:

From the Secretary of the Interior's Standards for Rehabilitation:

(9) New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.



(10) New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

From the Secretary of the Interior's Guidelines for Rehabilitating Historic Buildings (other SOI Guidelines may also apply):

Roofs

<u>Recommended:</u> Designing additions to roofs such as residential, office, or storage spaces; elevator housing; decks and terraces; or dormers or skylights when required by the new use so that they are inconspicuous from the public right-of-way and do not damage or obscure character-defining features.

<u>Not Recommended:</u> Changing the configuration of a roof by adding new features such as dormer windows, vents, or skylights so that the historic character is diminished.

Windows

<u>Not Recommended</u>: Installing new windows, including frames, sash, and muntin configuration that are incompatible with the building's historic appearance or obscure, damage, or destroy character-defining features.

Entrances/Porches

<u>Recommended</u>: Designing and installing additional entrances or porches when required for the new use in a manner that preserves the historic character of the buildings, i.e., limiting such alteration to non-character-defining elevations.

District or Neighborhood Setting

<u>Not Recommended</u>: Introducing new construction into historic districts that is visually incompatible or that destroys historic relationships within the setting.

From the City of Ann Arbor Design Guidelines:

Roofs

Not Appropriate: Adding chimneys, cupolas, or dormers where not appropriate.

Windows

Not Appropriate: Removing or radically changing a window that is important in defining the overall historic character of the property.

<u>Not Appropriate:</u> changing the number, location, and size or glazing pattern of window by cutting new openings, blocking in, and installing replacement sash that does not fit the historic opening.

STAFF FINDINGS:

- 1. The homeowners are reworking the interior floorplan to accommodate a ground-floor bedroom, enlarged bathroom, and a ramped entrance off the back for anticipated accessibility needs. There are currently two bedrooms upstairs. In addition, two dormers on the 1 ½ story rear wing of the house would convert a space that currently has 24" knee walls into a bedroom, closet, and ½ bath. By reworking the interior and making small changes to existing features of the house the homeowners are able to avoid proposing a potentially more impactful rear addition.
- 2. On the rear wing, staff believes the design of the shed dormers is inconspicuous and appropriate. On both sides they are stepped in from the rear corners of the house, and the original trim in both rear-facing gables is maintained. The chimney on the back of the house is red brick and has no distinctive character or architectural features. Its removal would allow the recapture of significant interior space on both floors. All windows on the dormers and a new window next to the rear balcony door are Andersen aluminum clad wood. Replacing the balcony door on the rear wing with a full-lite fiberglass door that fits the current opening is appropriate.
- 3. The windows facing south on the first-floor bumpout are not original. The one on the left in the application photograph has different proportions than those on the rest of the house. It is unclear whether the bumpout was previously a porch that was enclosed, or if it was always finished space. On the left-hand window, since neither the window nor the opening are original, and there is no evidence that a different-sized window used to be there, staff believes this window's removal is appropriate and doesn't affect the architectural integrity of the house. The right-hand window is more likely to be an original opening size. The proposed replacement is approximately the same width as the left-hand window (3'6") but is taller (approx. 4'1"). If the commission believes replacing this window with a larger one meets the standards and guidelines, then staff feels that the size of the replacement window is acceptable since it is taller than it is wide and will be the only window on that face of the bump out. The proposed replacement window is all wood.
- 4. The wood ramp along the south side of the house is simple and minimally intrusive. It is located on top of an existing concrete walkway and ties into the modern rear deck. It has 5/"4 x 6" treated decking and a handrail on each side. Staff would like the applicant to clarify at the meeting whether the ramp and/or handrail will be attached to the house, or whether it will be a free-standing structure.
- 5. Staff finds the work generally compatible in exterior design, arrangement, material, and relationship to the rest of the building and the surrounding area, and finds that it meets the Secretary of the Interior's Standards and Guidelines for Rehabilitation, and the Ann Arbor Historic District Design Guidelines.

POSSIBLE MOTIONS: (Note that the motion is only a suggestion. The Review Committee, consisting of staff and at least two Commissioners, will meet with the applicant on site and then make a recommendation at the meeting.)

I move that the Commission issue a certificate of appropriateness for the application at 217 Third Street, a contributing property in the Old West Side Historic District, to construct two shed dormers on the rear wing of the house, remove the chimney, remove

a non-original window and patch the opening with siding, enlarge a window opening, add a new window in a new opening, replace a back door, and add a ramp along the south side of the house. The work as proposed is compatible in exterior design, arrangement, texture, material and relationship to the rest of the building and the surrounding area and meets the *Ann Arbor Historic District Design Guidelines*, in particular the guidelines for roofs and windows, and the *Secretary of the Interior's Standards for Rehabilitation* and *Guidelines for Rehabilitating Historic Buildings*, in particular standards 9 and 10 and the guidelines for roofs, windows, porches, and neighborhood.

MOTION WORKSHEET:

I move that the Commission issue a Certificate of Appropriateness for the work at <u>217 Third Street</u> in the <u>Old West Side</u> Historic District

_____ Provided the following condition(S) is (ARE) met: 1) STATE CONDITION(s)

The work is generally compatible with the size, scale, massing, and materials and meets the Secretary of the Interior's Standards for Rehabilitation, standard(S) number(S) (circle all that apply): 1, 2, 3, 4, 5, 6, 7, 8, 9, 10

ATTACHMENTS: application, photos, drawings, window specs





City of Ann Arbor PLANNING & DEVELOPMENT SERVICES — PLANNING SERVICES


301 E. Huron Street | P.O. Box 8647 | Ann Arbor, Michigan 48107-8647 p. 734.794.6265 | f. 734.994.8312 | planning@a2gov.org

ANN ARBOR HISTORIC DISTRICT COMMISSION APPLICATION

[Section 1: Property Being Reviewed and Ownership Information
	Address of Property: 217 3rd Struf
	Historic District: 0 W.S
	Name of Property Owner (If different than the applicant):
	Address of Property Owner:
	Daytime Phone and E-mail of Property Owner:
7	Signature of Property Owner:Date:
	Section 2: Applicant Information
	Name of Applicant: Martha Markenzic
	Address of Applicant: 1105 Chestrut St
	Daytime Phone: (+34) 323,2012 Fax:()
	E-mail: Muffymackenzie@ 201. Com
	Applicants Deletions in to Deposity & super prohitors contactor other
	Signature of applicant:
	Section 3: Building Use (check all that apply)
	X Residential Single Family Multiple Family Rental
	Commercial Institutional
	Section 4: Stille-DeRossett-Hale Single State Construction Code Act (This item MUST BE INITIALED for your application to be PROCESSED)
	Public Act 169, Michigan's Local Historic Districts Act, was amended April 2004 to include the following language: "the applicant has certified in the application that the property where the work will be undertaken has, or will have before the proposed completion date, a a fire alarm or smoke alarm complying with the requirements of the Stille-DeRossett-Hale Single State Construction Code Act, 1972 PA 230, MCL 125.1501 to 125.1531."
	Please initial here: M(M)

	0
1. Provide a brief summary of proposed	
0 1 10110	and 2 dormers on the existing
2nd floor back roo	
existing chimney as e	well as removing 2 windows or
South Side that are i	not original and installing one wind
2. Provide a description of existing con-	ditions. The home has been wil
Cared for There	is a Kitchen that was verou
in the 700 or 800	and is not well laid out or
very functional.	
U	
3. What are the reasons for the propos	ed changes? The need for an open of
for the co-owner who	
office on the first tho	
	1 100 (1)
a scient upstairs but	throom and office. We with work
a second upstairs but	amily (elder parents) who come stay
home and we have for	
4. Attach any additional information that	amily (elder parents) who come stay
4. Attach any additional information that	amily (elder parents) who come stay
4. Attach any additional information that these attachments here.	at will further explain or clarify the proposal, and indicate
4. Attach any additional information that these attachments here. 5. Attach photographs of the existing page 1.	amily (elder parents) who come stay
4. Attach any additional information that these attachments here.	at will further explain or clarify the proposal, and indicate
4. Attach any additional information that these attachments here. 5. Attach photographs of the existing proposed work area.	at will further explain or clarify the proposal, and indicate
4. Attach any additional information that these attachments here. 5. Attach photographs of the existing proposed work area.	roperty, including at least one general photo and detailed
4. Attach any additional information that these attachments here. 5. Attach photographs of the existing proposed work area.	roperty, including at least one general photo and detailed
4. Attach any additional information that these attachments here. 5. Attach photographs of the existing properties of proposed work area. Date Submitted: Project No.: HDC	roperty, including at least one general photo and detailed STAFF USE ONLY Application toStaff orHDC
4. Attach any additional information that these attachments here. 5. Attach photographs of the existing properties of proposed work area. Date Submitted: Project No.: HDC	roperty, including at least one general photo and detailed STAFF USE ONLY Application toStaff orHDC Fee Paid:





LEGAL DESCRIPTION

LOT 4 OF, "KRAUSE'S ADDITION TO THE CITY OF ANN ARBOR", A PART OF THE SOUTHEAST QUARTER OF THE NORTHWEST QUARTER OF SECTION 29, T.2S., R.6E., CITY OF ANN ARBOR, WASHTENAW COUNTY, MICHIGAN, AS RECORDED IN LIBER 1 OF PLATS ON PAGE 22, WASHTENAW COUNTY RECORDS. SUBJECT TO EASEMENTS AND RESTRICTIONS OF RECORD.



LEGEND

000.00 = EXISTING ELEV.

000.00 = PROPOSED ELEV.

DRAINAGE COURSE

- SILT FENCE

F.G. = BRICK LEDGE

= EXISTING CONTOUR

PLOT PLAN

PREPARED FOR: MUFFY MACKENZIE 217 THIRD STREET ANN ARBOR, MI 48103 (734) 323–2013


JEKABSON & ASSOCIATES, P.C. Professional Land Surveyors 1320 Goldsmith, Plymouth, MI 48170 (734) 414–7200 (734) 414–7272 fax DATE 26 OCT 16
JOB NO. 16-08-015
SCALE 1" = 10'
DRAWN
JRN
CHECKED
JGE
SHEET 1 OF 1


REVISIONS




























WOOD ULTIMATE DOUBLE HUNG

CONSTRUCTION DETAILS



Masconry Opening

(9)

1/5, (13)

Frame Size


Rough Opening


HEAD JAMB AND SILL-OPERATOR

MARVIN KITCHEN WINDOW - WOOD EXTERIOR

HEAD JAMB AND SILL - OPERATOR WITH INTERIOR SHADE

Awning Window Details Scale 11/2" (38) = 1'-0" (305) - 1:8






ANDERSEN AWHING WINDOW @ BEDROOM - CLAD

• 4 %/16" (116) Jamb depth measurement is from backside of installation flange


Andersen.

400 SERIES

Woodwright* Double-Hung Window Details Scale $1^1/2^n$ (38) = 1^1-0^n (305) -1:8



Horizontal Section



ANDERSEN DOUBLE-HUNG @ DEDROOM DOOR AND BATH-CLAD

9.