## Storm Water Outfall Erosion Repairs at Huron Pkwy. & Hubbard

#### Exhibit - A

1. **Project Scope** – Repair existing 18" and 84" storm water outfalls located at the southeast corner of Huron Pkwy. & Hubbard Rd. intersection.

## 2. Existing Conditions

- 18" U-M storm water outfall
  - Serves a catchment area of about 24 acres mostly owned by U-M
  - o Failed manhole structure O-46
  - o Dislocated and rusted CMP outlet pipe
  - High velocity discharge
  - o Eroded channel
- 84" City storm water outfall
  - a. Serves a catchment area of about 750 acres owned by combination of City, U-M and privately owned residential & commercial land use
  - Scouring at the headwall
  - Undermining of foundation
  - o High velocity discharge
  - Concrete pipe joint separation


## 3. Repair Options

- 18" U-M storm water outfall
  - Option A Repair manhole O-46, install new drop structure and outlet pipe
  - Option B Replace manhole O-46 with a new drop structure, new outlet pipe (Recommended)
- 84" City storm water outfall
  - o Option C Riprap basin and cross vanes
  - Option D Riprap basin and cross vanes with live tree staking (Recommended)
- Common items for both outfall repairs
  - o Temporary sediment basin
  - o Gravel access drive from Huron Pkwy.
  - o ROW permit for access, staging & laydown
  - o Traffic control for lane closure and sidewalk closure on Huron Pkwy.
  - T&E species investigation
  - o EGLE permit JPA


#### 4. Project Schedule

- T&E species investigation : June-July 2020
- Design : July-September 2020 (DD, CD)
- EGLE permit : August-October 2020
- City of AA Review : July-September 2020
- Bid/Award : October 2020
- Construction Start : December 2020
- Project Completion : Spring 2021

# 5. Project Concept: Existing Conditions & Proposed Work



**Existing Conditions** 



Proposed Work