EQUIPMENT: 2503

TYPE OF EQUIPMENT: 3 Yard Dump YEAR: 2000

DIVISION: Field Services

MAKE OF EQUIPMENT: Ford PLATE: 597X34

DATE	Odometer	WORK PERFORMED ON #2503		
09\06\00	110	Set up new truck		
10\23\00	805	Replace mud flaps		
11\27\00	1110	Have rear springs reworked - Add extra rear lights - Adjust tarp system		
04\19\01	1211	Service call - Repair power tailgate		
09\26\01	2716	PM service – Repair front brakes		
12\07\01	3594	Take to dealer for recall		
01\03\02	3733	Replace rear hitch		
02\14\02	4112	Take to dealer for warranty work		
04\04\02	4235	Replace headlamp		
09\09\02	5600	PM service		
03\11\04	9060	PM service – Air filter		
09\22\04	10335	Repair tire		
11\05\04	10735	Repair dump box sides so they cant open		
03\22\05	11332	Replace top light – Replace wiring		
06\07\05	11960	PM service		
06\14\06	14310	Repair fuel system		
08\11\06	14615	PM service – Repair two tires		
08\17\06	14667	Complete rear brakes –Replaced front brake pads – Replace all tires		
10\25\06	15250	Replace battery – Repair electric motor for dump body hoist		
11\28\06	15600	Replace electric motor for dump box		
01\10\07	15735	Replace hydraulic tank		
03\05\07	16140	Replace idle air control valve		
-				
4				

DATE	Odometer	WORK PERFORMED ON #2503	

2503	Completion	Work Order	Work Requested	Corrective 0 HOURS
	Labor Material ntracted	35951 \$32.75 \$0.00 \$0.00		192 11/19/07 replaced rr bulb.from utilies stock
	12/20/2007 Labor Material ntracted	36436 \$98.25 \$0.00 \$0.00		200 12/19/07 completed insp. Maintenance
	12/6/2007 Labor Material ntracted	36121 \$32.75 \$2.26 \$0.00 \$35.01		Repairs in house
	12/6/2007 Labor Material ntracted	36118 \$196.50 \$18.79 \$0.00 \$215.29		192 completed insp. Maintenance
3/5/2007 Labor Material Contracted		32327 \$161.82 \$0.00 \$20.00		190 03/02/07 service call to turnberry sub. truck started and ran fine for me. followed to 2000 s.industrial. ok at this time. Repairs in house
	Total	\$563.12		

EQUIPMENT: 2504

TYPE OF EQUIPMENT: 3 Yard Dump YEAR: 2000

MAKE OF EQUIPMENT: Ford PLATE: 597X35

DIVISION: Field Services

PURCHASED FROM: Signature Ford PRICE: \$28,207 DEPRECIATED COST: \$40,032 DATE RECEIVED: 7-12-00

DATE	Odometer	WORK PERFORMED ON #2504
08\15\00	115	Set up new truck
10\06\00	510	Adjust tarp and top light
10\19\00	650	Replace front mud flaps
10\30\00	782	Have rear springs reworked - Add extra rear lights
01\22\01	1285	Replace turnsignal flasher
10\30\01	3795	PM service
12\10\01	4472	To dealer for recall
01\03\02	4670	Replace rear hitch
11\22\02	6900	PM service
09\16\03	8965	PM service
08\16\04	10777	Tire repair
09\08\04	11000	Repair tailgate – Repair sideboard
10\21\04	11210	Replace front bumper and grill
06\08\05	12300	PM service
09\08\05	13080	Replace (1) rear tire
11\28\05	13720	Repair gear shifter
06\14\06	15050	PM service
11\02\06	15800	Repair lights
01\18\07	16975	PM service – Replace hydraulic tank
07\27\07	18300	Replace right door mirror
		
· · · · · · · · · · · · · · · · · · ·		
		·
	·	·
·	· · · · · · · · · · · · · · · · · · ·	

DATE	Odometer	WORK PERFORMED ON #2504	
		·	

2504	ompletion Date	Work Order	Work Requested	Corrective Action	0 HOURS
1. Lab	/3/2008	36580 \$0.00	SCRAPER / Commercial Cost and Stock Requisition Slips ONLY	Misc. Supplies and Charges	
Mater	ial	\$2.03			
Contract	ed	\$0.00			
		\$2.03			
12/2 Lab	20/2007 or	36414 \$163.75	SHOP REQUESTFor Purchase Inspections ONLY	200 12/18/07 completed insp. M	Maintenance
Mater	ial	\$0.00			
Contract	ed	\$0.00			
		\$163.75			
12	/7/2007	36117	150 HOUR "A" INSPECTION M=19,728	192 12/05/07 completed insp. M	Maintenance
Lab	or	\$163.75	,		
Mater	ial	\$18.79			
Contract	ed	\$0.00			
		\$182.54	·		
9/1	19/2007	35092	DRIVER'S REQUEST. motor oil	Misc. Supplies and Charges	
Lab	or	\$0.00			
Mater	ial	\$4.34			
Contract	ed	\$0.00			
		\$4.34			
Tot	al \$	352.65		٧	