Description and Reasons for Front Porch Replacement At 514 W. Madison St., Ann Arbor

The homeowner at the above address has requested from Dexter Block to replace the existing foundation and front porch decorative block walls, columns, steps, and porch cap. He states that "the foundation is crumbling and pulling away from the house". Dexter Block did a visual inspection of front porch and did find evidence of pulling away from the house and block deterioration around foundation walls and steps. Also noticed cracks in the porch and column caps. This deterioration would suggest that the foundation to the front porch has sunk over the years and requires replacement. We would not be able to effectively remove the existing block intact and in a condition that is structurally sound due to their current deteriorated condition.

For Dexter Block to ensure proper structurally sound replacement of porch would fully remove existing porch cap, steps, block walls, and footings. Then rebuild, in the **same footprint and height**, the front porch leaving the existing ceiling & roof structure in place.


Rebuild would include supporting existing roof structure, pouring new footings, install similar decorative hand-hewn blocks for walls and columns, and finally pour new steps and cap. Once completed the existing porch post would be reinstalled on the new block columns.


I've included permit drawings and pictures of existing conditions, deterioration, and visual of old existing block and new proposed block. If any additional information is needed, please let us know so we can assist the owner with the front porch issues.

Adam Shell

Dexter Block/Builders


ASHELL@DEXTERBUILDERS.COM







DEXTER BUILDERS	Front Porch		Moen Madison St or, MI 48103		
		(734) 223-6479 zakmoen@hotmail.com			
13600 Luick Dr Chelsea, MI 48118	Foundation		Job #225280		
734-426-3852 dexterbuilders.com	Scale: as shown		9/23/22		







Extg Demo Plan

Scale as Shown


DEXTER	Front Porch	514 V	hary Moen W Madison St Arbor, MI 48103		
BUILDERS		(734) 223-6479 zakmoen@hotmail.com			
13600 Luick Dr Chelsea, MI 48118	Demo/Foundation		Job #225280		
734-426-3852 dexterbuilders.com	Scale: as show	wn 8/17/22 <i>Pg.</i>		1	








DEXTER	Front Porch	514 V	ichary Moen 4 W Madison St In Arbor, MI 48103		
BUILDERS		(734) 223-6479 zakmoen@hotmail.com			
13600 Luick Dr Chelsea, MI 48118	Floor Plan		Job #225280		
734-426-3852 dexterbuilders.com	Scale: as show	wn 8/17/22 Pg. 2		2	



 $\sqrt{\frac{}{2}}$

Proposed East/West Section View

Scale as Shown






Proposed North/South Section View

Scale as Shown

DEXTER	Front Porch	514 V	chary Moen I W Madison St n Arbor, MI 48103			
BUILDERS		(734) 223-6479 zakmoen@hotmail.com				
13600 Luick Dr Chelsea, MI 48118			Job #225	280		
734-426-3852 dexterbuilders.com	Scale: as shown		8/17/22	Pg. 3		



DEXTER	Front Porch	514 V	nary Moen W Madison St Arbor, MI 48103		
BUILDERS		(734) 223-6479 zakmoen@hotmail.com			
13600 Luick Dr Chelsea, MI 48118	Proposed Rendering		Job #225280		
734-426-3852 dexterbuilders.com	Scale: as shown		8/17/22	Pg.	1





















