ANN ARBOR HISTORIC DISTRICT COMMISSION

Staff Report

ADDRESS: 834 West Washington Street, Application Number HDC12-047

DISTRICT: Old West Side Historic District

REPORT DATE: April 30, 2012

REPORT PREPARED BY: Katie Remensnyder, Interim Historic Preservation Coordinator

REVIEW COMMITTEE DATE: Monday, May 7 for the Thursday, May 10, 2012 HDC meeting

OWNER APPLICANT

Name: Ariel Adamson & James Jilek Renewal by Andersen/RBA Minnesota

Address: 834 W Washington St 37720 Amrhein Drive

Ann Arbor, MI 48103 Livonia, MI 48150 **Phone:** (734) 678-6614 (734) 237-1052

BACKGROUND: This front gable two-story vernacular house features cornice returns and a porch spanning the south (front elevation) with Doric columns. The house was build in 1911 and the first residents were Otto and Amanda Toney. Otto Toney is listed in the 1911 Polk City Directory as a carpenter.

LOCATION: The site is located on the north side of West Washington Street, between South Seventh Street and Third Street.


APPLICATION: The applicant seeks HDC approval to replace thirteen existing wood windows with Renewal by Andersen energy efficient windows and replace the exterior trim around each window.

APPLICABLE REGULATIONS

From the Secretary of the Interior's Standards for Rehabilitation:

(6) Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.

From the Secretary of the Interior's Guidelines for Rehabilitating Historic



Buildings (other SOI Guidelines may also apply):

<u>Recommended:</u> Identifying, retaining, and preserving windows – and their functional and decorative features – that are important in defining the overall historic character of the building. Such features can include frames, sash, muntins, glazing, sills, heads, hoodmolds, paneled or decorated jambs and molding, and interior and exterior shutters and blinds.

Repairing window frames and sash by patching, splicing, consolidating or otherwise reinforcing. Such repair may also include replacement in kind of those parts that are either extensively deteriorated or are missing when there are surviving prototypes such as architraves, hoodmolds, sash, sills, and interior or exterior shutters and blinds.

Replacing in kind an entire window that is too deteriorated to repair – if the overall form and detailing are still evident – using the physical evidence to guide the new work. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

Not Recommended: Retrofitting or replacing windows rather than maintaining the sash, frame, and glazing.

Replacing an entire window when repair of materials and limited replacement of deteriorated or missing parts are appropriate.

Removing or radically changing windows which are important in defining the overall historic character of the building so that, as a result, the character is diminished.

Changing the historic appearance of windows through the use of inappropriate designs, materials, finishes, or colors which noticeably change the sash, depth of reveal, and muntin configuration; the reflectivity and color of the glazing; or the appearance of the frame.

Obscuring historic window trim with metal or other material.

Installing new windows, including frames, sash, and muntin configuration that are incompatible with the building's historic appearance or obscure, damage, or destroy character-defining features.

From the Secretary of the Interior's Standards for Rehabilitation & Illustrated Guidelines on Sustainability for Rehabilitating Historic Buildings

Windows

Recommended: Maintaining windows on a regular basis to ensure that they function properly and are completely operable.

Retaining and repairing historic windows when deteriorated.

Weather stripping and caulking historic windows, when appropriate, to make them weather tight.

Installing interior or exterior storm windows or panels that are compatible with existing historic windows.

Not recommended: Neglecting to maintain historic windows and allowing them to deteriorate beyond repair with the result that they must be replaced.

Removing repairable historic windows and replacing them with new windows for perceived improvement in energy performance.

Replacing repairable historic windows with new insulated windows.

STAFF FINDINGS

- 1. The windows that are proposed to be replaced are located on all four elevations and are character-defining features of the house. Based on submitted photographs, there appears to be a small amount of rot present on at least one window. The applicant states that other windows exhibit some amount of rot, loss of glazing compound, and water infiltration. Staff has not yet visited the site to review the windows and no assessment of each individual window has been submitted at the time this report was prepared.
- 2. The cost estimate for the replacement of the thirteen windows has not been submitted. Similarly, estimates for preservation-based solutions (such as the repair of some or all of the windows, the installation of storm windows, etc) have not been submitted.
- 3. Staff will make a recommendation at the HDC meeting regarding these windows, after a comprehensive review of their condition is completed at the Review Committee visit.

POSSIBLE MOTIONS: (Note that the motion is only a suggestion. The Review Committee, consisting of staff and at least two Commissioners, will meet with the applicant on site and then make a recommendation at the meeting.)

I move that the Commission issue a certificate of appropriateness for the application at 834 West Washington Street, a contributing property in the Old West Side Historic District, to allow the replacement of thirteen windows and exterior trim. The proposed work is compatible in exterior design, arrangement, texture, material and relationship to the surrounding resources and meets *The Secretary of the Interior's Standards for Rehabilitation* and *Guidelines for Rehabilitating Historic Buildings*, in particular standard 6, and the Guidelines for Windows.

MOTION WORKSHEET:

I move that the Commission issue a Certificate of Appropriateness for the work at <u>834 West Washington Street</u> in the <u>Main Street</u> Historic District

____ Provided the following condition(S) is (ARE) met: 1) STATE CONDITION(s)

The work is generally compatible with the size, scale, massing, and materials and meets the Secretary of the Interior's Standards for Rehabilitation, standard(S) number(S) (circle all that apply): 1, 2, 3, 4, 5, 6, 7, 8, 9, 10

ATTACHMENTS: application, drawings, photos.



City of Ann Arbor PLANNING & DEVELOPMENT SERVICES — PLANNING SERVICES

100 North Fifth Avenue | P.O. Box 8647 | Ann Arbor, Michigan 48107-8647 p. 734.794.6265 | f. 734.994.8312 | planning@a2gov.org

ANN ARBOR HISTORIC DISTRICT COMMISSION APPLICATION

Section 1: Property Being Reviewed and Ownership Information			
Address of Property: 834 W Washington Street			
Historic District:			
Name of Property Owner (If different than the applicant):			
Ariel Adamson & James Jilek			
Address of Property Owner: 834 W Washington Street			
Daytime Phone and E-mail of Property Owner: 734-678-6614 - Ariel			
Signature of Property Owner:			
Section 2: Applicant Information			
Name of Applicant: Renewal by Andersen/RBA Minnesota			
Address of Applicant: 37720 Amrhein Drive, Livonia, MI 48150			
Daytime Phone: (734) 237-1052 Fax:(734) 464-7084			
E-mail:			
Applicant's Relationship to Property:ownerarchitect _X _contactorother			
Signature of applicant:			
Section 3: Building Use (check all that apply)			
X Residential X Single Family Multiple Family Rental			
Commercial Institutional			
Section 4: Stille-DeRossett-Hale Single State Construction Code Act (This item MUST BE INITIALED for your application to be PROCESSED)			
Public Act 169, Michigan's Local Historic Districts Act, was amended April 2004 to include the following language: "the applicant has certified in the application that the property where the work will be undertaken has, or will have before the proposed completion date, a a fire alarm or smoke alarm complying with the requirements of the Stille-DeRossett-Hale Single State Construction Code Act, 1972 PA 230, MCL 125.1501 to 125.1531." Please initial here:			



City of Ann Arbor PLANNING & DEVELOPMENT SERVICES — PLANNING SERVICES

100 North Fifth Avenue | P.O. Box 8647 | Ann Arbor, Michigan 48107-8647 p. 734.794.6265 | f. 734.994.8312 | planning@a2gov.org


ANN ARBOR HISTORIC DISTRICT COMMISSION APPLICATION


Section 1: Property Being Reviewed and Ownership Information
Address of Property: 834 W Washington Street
Historic District:
Name of Property Owner (If different than the applicant):
Address of Property Owner: 834 Washington Street
Daytime Phone and E-mail of Property Owner: (734) 678-6614 / arieladamson 69mail.com
Signature of Property Owner:
Section 2: Applicant Information
Name of Applicant:
Address of Applicant: 37730 Amrhein
Daytime Phone: (134) 237-1070 Fax:(134) 464-7084
E-mail:
Applicant's Relationship to Property:ownerarchitect X_contactorother
Signature of applicant: Date:
Section 3: Building Use (check all that apply)
X Residential Single Family Multiple Family Rental
Commercial Institutional
Section 4: Stille-DeRossett-Hale Single State Construction Code Act (This item MUST BE INITIALED for your application to be PROCESSED)
Public Act 169, Michigan's Local Historic Districts Act, was amended April 2004 to include the following language: " the applicant has certified in the application that the property where the work will be undertaken has, or will have before the proposed completion date, a a fire alarm or smoke alarm complying with the requirements of the Stille-DeRossett-Hale Single State Construction Code Act, 1972 PA 230, MCL 125.1501 to 125.1531." Please initial here:

Section 5: Description of Proposed Changes (attach additional sheets as necessary)	
1. Provide a brief summary of proposed changes. Replace existing wood	
windows with Renewal by Anderson energy efficient	
windows. Insulate with low expantion form, fill	
weight pockets with insulation, recap exterior	
term replace exterior trun aroun each window	
2. Provide a description of existing conditions. Execting windows have	
some rotting issues as well as mold. Some glazing	
compound is missing. Windows do not operate property,	
they eve very drafty and several have water	
leakage problems	
3. What are the reasons for the proposed changes? Lostomer needs	
energy efficiency as well as low maintenance	
and the filt in 525h will allow for easy	
Cleaning. Need to stop water infilitration and air draft S	<i>'</i> .
4. Attach any additional information that will further explain or clarify the proposal, and indicate	
these attachments here. Lenewal by Andersen offers the most energy efficient window	200
19 State of	
vorked in many Historic Districts in Mich as well as the res	stot
1	the count
5. Attach photographs of the existing property, including at least one general photo and detailed photos of proposed work area.	WORT


STAFF USE ONLY				
Pate Submitted:	Application toH		orHDC	
Project No.: HDC	Fee Paid:	25° + 35°		
Pre-filing Staff Reviewer & Date:	Date of Public Hearing:			
Application Filing Date:	Action:	HDC COA	HDC Denial	
Staff signature;		HDC NTP	Staff COA	
Comments:				

Section 5: Description of Proposed Changes (attach additional sheets as necessary)				
Provide a brief summary of proposed changes				
Replace 13 windows in home				
Provide a description of existing conditions				
	404			
3. What are the reasons for the proposed changes?				
A STATE OF THE STA				
4. Attach any additional information that will further ethese attachments here.	explain or clarify the proposal, and indicate			
 Attach photographs of the existing property, including at least one general photo and detailed photos of proposed work area. 				
STAFF USE C	DNLY			
Date Submitted:	Application toStaff orHDC			
Project No.: HDC				
Pre-filing Staff Reviewer & Date:				
Application Filing Date:				
Staff signature:				
Comments:				












102 LIVING ROOM




103 DINING ROOM




104 DINING DOOL




105 KITCHEN




#201 STAIRS (TEMPERED GLASS)




#202 BEDROOM (CLOSET)




#203 BEDROOM (CLOSET)




#204 MASTER BEDROOM




#205 MASTER BEDROOM



#206 BEDROOM #2



#207 BEDROOM #2



#208 BATHROOM

