TABLE 1-1. OPERATIONAL RUNWAY CONDITION ASSESSMENT MATRIX (RCAM) BRAKING ACTION CODES AND DEFINITIONS

Assessment Criteria		Control/Braking Assessment Criteria	
Runway Condition Description	RwyCC	Deceleration or Directional Control Observation	Pilot Reported Braking Action
• Dry	6	<u></u>	
<ul> <li>Frost</li> <li>Wet (Includes damp and 1/8 inch depth or less of water)</li> <li>1/8 inch (3mm) depth or less of:</li> <li>Slush</li> <li>Dry Snow</li> <li>Wet Snow</li> </ul>	5	Braking deceleration is normal for the wheel braking effort applied AND directional control is normal.	Good
-15°C and Colder outside air temperature:  • Compacted Snow	4	Braking deceleration OR directional control is between Good and Medium.	Good to Medium
Slippery When Wet (wet runway) Dry Snow or Wet Snow (any depth) over Compacted Snow  Greater than 1/8 inch (3 mm) depth of: Dry Snow Wet Snow  Warmer than -15°C outside air temperature: Compacted Snow	3	Braking deceleration is noticeably reduced for the wheel braking effort applied OR directional control is noticeably reduced.	Medium
Greater than 1/8 inch(3 mm) depth of:  Water Slush	2	Braking deceleration OR directional control is between Medium and Poor.	Medium to Poor
• Ice	1	Braking deceleration is significantly reduced for the wheel braking effort applied OR directional control is significantly reduced.	Poor
Wet Ice     Slush over Ice     Water over Compacted Snow     Dry Snow or Wet Snow over Ice	0	Braking deceleration is minimal to non-existent for the wheel braking effort applied OR directional control is uncertain.	Nil

Note: The unshaded portion of the RCAM is associated with how an airport operator conducts a runway condition assessment.

Note: The shaded portion of the RCAM is associated with the pilot's experience with braking action.

Note: The Operational RCAM illustration will differ from the RCAM illustration used by Airport Operators.

Note: Runway condition codes, one for each third of the landing surface, for example 4/3/3, represent the runway condition description as reported by the airport operator. The reporting of codes by runway thirds is expected to begin in October of 2016.