HBA16.00Z



# City of Ann Arbor 4-18-16 PLANNING & DEVELOPMENT SERVICES — CONSTRUCTION SERVICES

Mailing: 301 E. Huron St. P.O. Box 8647 Ann Arbor, Michigan 48107-8647 p. 734.794.6263 | f. 734.994.8460 | building@a2gov.org

### APPLICATION FOR VARIANCE - BUILDING BOARD OF APPEALS

Section 1: Applicant Information
Name of Applicant: Wessinger Properties - Nick Else
Address of Applicant: 2061 5.72 Sh.
Daytime Phone: 754 747 6372 Fax: 734 747 - 8542
Email: Wessingerproperties equal. com
Applicant's Relationship to Property:
Section 2: Property Information
Address of Property: 818 Church St. Apt. 2 + Apt. 2
Zoning Classification: R4C
Tax ID# (if known): 09-09-33-203-006
*Name of Property Owner:  *If different than applicant, a letter of authorization from the property owner must be provided.
Section 3: Request Information
☑ Variance
Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested:
Please see attached sheets.
Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26
Give a detailed description of the work you would need this variance for (attach additional sheets if necessary)
No work needed. All areas are as existing since
our ownership of the build. Also attacked are
staff notes and a cellar marks of filled out by
Rita Fulton in 2009.

Section 4: Variance Request
The City of Ann Arbor Building Board of Appeals has the codes. A variance may be granted by the Building Board of Appeals only in cases involving practical difficulties or unnecessary hardships when <b>ALL</b> of the following is found <b>TRUE</b> .
Please provide a complete response to each item below. These responses, together with the required materials in Section 5 of this application, will form the basis for evaluation of the request by staff and the Building Board of Appeals.
1. Are there hardships or practical difficulties to complying with the Code? Are these hardships or practical difficulties an exception or unique to the home compared to other homes in the City?
Yes. It would not be possible to alter most of
The existing conditions without considerable expense.
2. Are the hardships or practical difficulties more than mere inconvenience or inability to obtain a
higher financial return, or both? (explain) Both Changing board room Alone
would not be a practical often.
3. What effect will granting the variance have on the neighboring properties? Nonc
4. What physical characteristics of your property in terms of size, shape, location or topography prevent you from using it in a way that is consistent with the Code?  These cellar rooms are existing and would be very safe as sleeping rooms in their current configuration.
5. Is the condition which prevents you from complying with the ordinance self-imposed? How did the condition come about?
configuration since prior to our ownership of the
building.
Section 5: Required Materials
The following materials are required for all variance requests in an <b>incomplete application</b> and will delay staff review and Building Board of Appeals consideration of the request. The materials listed below must accompany the application and constitute an inseparable part of the application. All materials must be provided on 8 ½" by 11" sheets. If incomplete, you will be scheduled for the NEXT MEETING DATE ON THE FOLLOWING MONTH.
State proposed use of property, size of lot and size and type of proposed changes.
☐ Building floor plans showing interior rooms, including dimensions. (continued)
☑ Photographs of the property and any existing buildings involved in the request.
Any other graphic or written materials that support the request.
Letter of Authority if being represented by someone other than the property owner.

Section 6: Acknowledgement	
SIGNATURES MUST BE SIGNED IN PRESENC	E OF NOTARY PUBLIC
I, the applicant, request a variance from the above named Cha City Code and/or 2006 Michigan Residential Code and/or 2006 reasons, in accordance with the materials attached hereto.	pter(s) and Section(s) of the Applicable 6 Michigan Building node for the stated
734 747 6372 Phone Number	911
	Signature
Wessingerproperties panail.com Email Address	Nick Els(
I, the applicant, hereby depose and say that all of the aforeme	
contained in the materials submitted herewith are true and correct dates, deadlines and instructions. Applicant acknowledges that and will not receive further notification of meeting dates and time when and where the meeting is and to appear to present their applicant.	and have received all coversheets with they are aware of these meeting dates les. All applicants are expected to know
	Signature
Further, I hereby give City of Ann Arbor Planning and Developmenthe Building Board of Appeals permission to access the subject pariance request. As a condition of granting any variance, the reinstating, paying fees for or acquiring new permits to inspect a property:	property for the purpose of reviewing my property owner is also responsible for and final out any putstanding work at this
On this day of 2016, bet named applicant and made oath that he/she has read the fore and knows the contents thereof, and that the same is true as to h matters therein stated to be upon his information and belief as to be true.	is/her own knowledge except as to those
manage 1/5	
PHILLIP D COOK JR  Notary Public: - Michigan  Washtenaw County  My Commission Expires, Jun 27, 2018	Not Tublic Signature  D. Cook To.
Not: Not (STIP) 、	Print Name
Date Submitted: 4-18-16 STAFF USE ONLY Fee Paid: Fee Paid:	C00.00
Pre-Filing Review Person & Date:	
Secondary Staff Review Person & Date	
Date of Public Hearing.	
BBA Action:	
OUSTANDING PERMITS:	





### CITY OF ANN ARBOR

100 N. FIFTH AVE • ANN ARBOR, MI 48104 (734) 794-6267

Receipt Number: 2016-00050279

**Project Number** 

BBA16-013

Receipt Print Date:

04/18/2016

Address

818 CHURCH ST

Applicant

WESSINGER PROPERTIES, LLC

Owner

WESSINGER PROPERTIES, LLC

Project Description

basement variance for 3 bedrooms

### **FEES PAID**

0026-033-3370-0000-4361

P&D - APPEAL FEES 15/16

BBA - ALL OTHER STRUCTURES

0026-033-3370-0000-4361

500.00

Total Fees for Account 0026-033-3370-0000-4361:

500.00

TOTAL FEES PAID

500.00

DATE PAID: Monday, April 18, 2016

PAID BY: LOGOS

PAYMENT METHOD: CHECK 3898

### Housing Variance requests for 818 Church Street Apartments 1 and 2.

I, Nick Else, on behalf of Wessinger Properties, am requesting that the following housing variances be granted for three existing cellar study rooms so that they can be used as legal sleeping rooms. All three rooms are existing, and have been in their current configuration and state of finish since before we purchased the building in 1985. In 2009, my father, John Wessinger, who founded and was running Wessinger Properties at the time, initiated steps to have these variances considered by the HBA. He asked housing inspector Rita Fulton to do a review of the spaces and write up staff notes that could accompany the variance request. These notes are attached to this application. Unfortunately, my father was fighting cancer at the time and he succumbed to the illness in 2010. At that time, I was thrust into taking over the family business and I was not aware of his intentions in regards to this housing variance request until recently. While checking into the current certificate of occupancy, I realized that the CO had actually expired and he never submitted the variance request paperwork.

Over the last month, we have had Protech Environmental provide Radon testing and have had the main sewer line (located in a separate mechanical room) cleaned by Roto-Rooter. Proof of these services, and the results, are attached to this request. I have also included two drawings for reference. The circled numbers on the drawings correspond with item numbers in this letter. Please note that there is no longer a ventilation issue for any of these rooms, as 3 small, non-opening foundation windows have been replaced with sliders since Rita Fulton's staff notes were written (see item A on both drawings 1 and 2.)

### Requested variances for Apartment 1 cellar study (please refer to drawing 1 for reference);

- 1. 8:504 (3)(a)
  - o Requirement: 2<sup>nd</sup> means of egress.
  - O Proposed: Through a mechanical room with no ceiling, accessed directly from the cellar room through a self-closing, 32" fire door. The mechanical room has an existing overhead sprinkler. We have also already installed wireless, interconnected smoke detectors at the top and bottom of the basement stairs.
- 2. 8:504 (4)(b)(1)
  - o Requirement: 27" minimum stairway width.
  - Proposed: 25". Current tread width measurement at the lower landing from 1<sup>st</sup> floor to cellar room. Overall stairway width is 37".
- 3. 8:503 (6)(n)
  - o Requirement: 22" required minimum at top of stairway.
  - Proposed: 21". Existing clear opening width of door opening at the top of cellar stairs.
- 4. 8:503 (6)
  - o Requirement: 3'6" floor to grade height.
  - o Proposed: 4'9". Existing floor to grade height. There is a large, existing slider window that has a clear opening measurement of 18 %" x 30 %" and a floor to sill height

of 50  $\frac{1}{2}$ " for egress access. With an exterior window well that is only 14" deep and is 29" x 59".

A Radon test was completed on 3/4/2016 by Protech and the result was a reading of 8.5 for this room which would require a Radon mitigation system. Protech has already received a signed proposal for installing this system and is in the process of scheduling the work (see tem B on drawing 1.) This will most likely occur sometime in May 2016.

Requested variances for Apartment 2 west cellar study (please refer to drawing 2 for reference);

### 5. 8:504 (3)(a)

- o Requirement: 2<sup>nd</sup> means of egress.
- o Proposed: Through a mechanical room with no ceiling, accessed directly from the unit cellar corridor through a self-closing 32" fire door. The basement corridor immediately outside this west cellar room has an existing drywall ceiling and sprinkler head and the mechanical room does not have a ceiling but also has an existing overhead sprinkler head. We have also already installed wireless, interconnected smoke detectors at the top and bottom of the cellar stairs of apt. 2.

### 6. 8:504 (4)(b)(2)

- o Requirement: 6'0" minimum headroom height at base of stairway.
- o Proposed: 5'9". Existing headroom at bottom of cellar stairs.

#### 7. 8:504 (4)(a)(2)

- o Requirement: 6'6" minimum headroom in corridor outside cellar room.
- o Proposed: 6'4". Existing headroom in cellar corridor outside of room.

### 8. 8:503 (6)

- o Requirement: 3'6" floor to grade height.
- o Proposed: 4'9". Existing floor to grade height. There is a large, existing slider window that has a clear opening measurement of 18 3" x 30 %" and a floor to sill height of 50 %" for egress access. With an exterior window well that is only 14" deep and is 29" x 111".

A Radon test was completed on 3/4/2016 by Protech and the result was a reading of 1.3 which is well under the government hazardous standard.

Requested variances for Apartment 2 west cellar study;

#### 5. 8:504 (3)(a)

- o Requirement: 2<sup>nd</sup> means of egress.
- o Proposed: Through a mechanical room with no ceiling, accessed directly from the unit cellar corridor through a self-closing 32" fire door. The basement corridor immediately outside this west cellar room has an existing drywall ceiling and sprinkler head and the mechanical room does not have a ceiling but also has an existing overhead

sprinkler head. We have also already installed wireless, interconnected smoke detectors at the top and bottom of the cellar stairs of apt. 2.

### 6. 8:504 (4)(b)(2)

o Requirement: 6'0" minimum headroom height at base of stairway.

o Proposed:

5'9". Existing headroom at bottom of cellar stairs.

### 7. 8:504 (4)(a)(2)

o Requirement: 6'6" minimum headroom in corridor outside cellar room.

o Proposed:

6'4". Existing headroom in cellar corridor outside of room.

#### 8. 8:503 (6)

o Requirement: 3'6" floor to grade height.


o Proposed: 4'9". Existing floor to grade height. There is a large, existing slider window that has a clear opening measurement of 18 ¾" x 30 ½" and a floor to sill height of 50 ½" for egress access. With an exterior window well that is only 14" deep and is 29" x 111".


A Radon test was completed on 3/4/2016 by Protech and the result was a reading of 1.5 which is well under the government hazardous standard.


In conclusion, we believe, and so did Rita Fulton, that these cellar rooms are safe and meet the spirit of the code for resident comfort and safety. Additionally, the existing ceiling mounted sprinkler heads and wireless, interconnected smoke detectors, add to resident safety. I look forward to addressing any questions you may have.

Nick Else

Owner/ Manager- Wessinger Properties







## **Wessinger Properties**


### Nick Else

Supplemental pictures for Housing Board of Appeals variance application submitted April 18, 2016.


The Item # on each picture refers to the variance requested in the application.




Item 1- Unit 1- Proposed 2nd means of egress from cellar room into mechanical room. 32' self-closing solid core fire door.




Item 2- Unit 1 cellar stairs. 25" tread-width at bottom of stairs. Wireless, interconnected smoke detectors are at the top and bottom of stairs.




Item 3- Unit 1- Door opening at top of cellar stairs. Existing clear opening of 21". Wireless, interconnected smoke-detectors are at the top and bottom of stairs.




Item 4- Unit 1- Exisitng slider window for cellar room egress with clear opening of 18 3/4" x 30 1/2" and sill height of 50 1/2"




Item 5- Unit 2- Proposed 2nd means of egress through mechanical room with ceiling mounted sprinkler. Through self-closing, solid core door.




Item 6- Unit 2- 5'9" exisitng headroom at bottom of stairs. Wireless, interconnected smoke detectors are at the top and bottom of stairs.



Item 7- Unit 2- 6'4" existing headroom outside of cellar rooms.



Item 8- Unit 2- Existing slider window in W cellar room for egress with clear opening of 18 3/4" x 30 1/2" and sill height of 50 1/2".



Item 8- Unit 2- Existing slider window in E cellar room for egress with clear opening of 18 3/4" x 30 1/2" and sill height of 50 1/2".



CITY OF ANN ARBOR, MICHIGAN Community Services Area Planning & Development Services Unit 301 E Huron St, Ann Arbor, MI 48107-8647 www.a2gov.org

### **Housing Board of Appeals Staff Report**

Subject: HBA 16-002

818 Church Street, Apartments 1 & 2 cellar bedrooms

### **Description and Discussion:**

The owner of the residence located at 818 Church Street requests several variances to allow three finished rooms in the cellar for use as sleeping rooms. One of the rooms is contained within apartment #1. Two of the rooms are contained within apartment #2.

Per inspector Rita Fulton's 7-24-2009 letter the following housing code deficiencies were identified:

### **GENERAL**

- G1. Inadequate natural ventilation for all 3 proposed cellar bedrooms per 8:502(2).
- G2. Inadequate second means of egress for all three proposed cellar bedrooms per 8:504(3)(a).
- G3. Inadequate grade for all three proposed cellar bedrooms per 8:503(6).
- G4. Radon tests showing acceptable levels of radon per 8:503(6)(s).
- G5. Proof of a recent sanitary sewer cleaning per 8:503(6)(g).

### APARTMENT #1 (1 cellar sleeping room proposed)

- A1.1 Inadequate width of the unit's interior cellar stairs at the lower stair landing per 8:504(4)(b)(1).
- A1.2 Inadequate doorway width at the top of the unit's interior cellar stairs, per 8:503(6)(n).

### APARTMENT #2 (2 cellar sleeping rooms proposed)

- A2.1 Inadequate ceiling height at the bottom of the unit's interior cellar stairs per 8:504(4)(b)(2).
- A2.2 Inadequate corridor headroom in the unit's cellar hallway per 8:504(4)(a)(2).

### Status of the above items is as follows:

- G1. This item was resolved with 3 replacement cellar sliding windows: Variance no longer required.
- G2. The second means of egress through the mechanical/laundry room lacks a 1-hour rated ceiling. The petitioner has wireless interconnect smoke alarms on the stairs, and an overhead sprinkler in the mechanical room.
- G3. The rooms are more than half below grade by 1-foot 3-inches and therefore defined as cellar rooms per 8:500(7). The housing board of appeals must approve use of the rooms as habitable space per 8:503(6).
- G4. EPA protocol tests performed by Protech from 3-2-16 to 3-4-16 show acceptable levels of radon in the 2 cellar rooms of apartment #2 (1.3 & 1.5 pCi/L), but exceed the 4 pCi/L threshold in the cellar room of apartment #1 (8.5 pCi/L). Permit BLDG16-0612 was issued on 4-14-16 to install a fan driven radon mitigation system.
- G5. Roto-Rooter cleaned the sewer on 3-1-16.
- A1.1 The cellar stair width is 2 inches short of the required 27 inch width at the lower stair landing. Structural constraints limit the ability to expand the landing.
- A1.2 The doorway width is 1 inch short of the required 22 inch width at the top of cellar stairs. Structural constraints limit the ability to widen the doorway.

A2.1 The ceiling height at the bottom of cellar stairs is 1 inch short of the required 6 foot height.

A2.2 The dwellings cellar corridor height outside the rooms is 2 inches short of the 6-foot 6-inch height requirement.

### Section 8:515 (2) of the Ann Arbor Housing Code:

The City of Ann Arbor Housing Code allows the Housing Board of Appeals to grant variances on existing structural elements of a building.

### **Standards for Approval:**

The variances do not violate the intent of this chapter

The first purpose of the Ann Arbor Housing Code is to protect the health, safety and welfare of residents. Granting these variances as requested by the petitioner **will not** violate this purpose.

### Recommendation:

Staff recommends the following motions:

G1. Ventilation 8:502(2).

No action required.

G2. Second means of egress 8:504(3)(a).

Staff is not opposed to the variance provided that interconnected smoke alarms are maintained at the top and bottom of cellar stairs, the overhead sprinkler is maintained within the mechanical room, and a carbon monoxide detector is maintained within the mechanical room.

G3. Grade 8:503(6).

Staff is not opposed to granting a variance for cellar sleeping rooms.

G4. Radon 8:503(6)(s).

A radon test should be performed within apartment #1 cellar after the installation of the radon mitigation system to ensure safe levels of radon have been achieved prior to occupancy of the apartment #1 cellar space.

G5. Sewer cleaning 8:503(6)(q).

No action required.

### A1.1 & A1.2 Stair and doorway width 8:504(4)(b)(1) and 8:503(6)(n).

Staff is not opposed to the variances and recommends a contingency to maintain interconnected smoke alarms at the top and bottom of the apartment #1 stairs.

A2.1 & A2.2 Ceiling height at stairs and corridor per 8:504(4)(b)(2) and 8:504(4)(a)(2).

Staff is not opposed to the variances and recommends a contingency to maintain interconnected smoke alarms at the top and bottom of the apartment #2 stairs.

### **MOTION**

Respectfully submitted,

Brad Ruppel
Development Services Inspector

Lisha Turner-Tolbert Inspection Supervisor



### CITY OF ANN ARBOR, MICHIGAN

Community Services Area
Planning & Development Services Unit
301 East Huron, P.O. Box 8647,
Ann Arbor, Michigan 48107-8647
Phone: (734) 794-6264
Fax: (734) 994-8460

September 8, 2016

Nick Else Wessinger Properties 2061 S. 7<sup>th</sup> Street Ann Arbor, MI 48103

Re:

818 Church Street Apt. 1 and Apt. 2, Ann Arbor, Michigan 48103

Parcel Identification Number ("PIN"): 09-09-33-203-006

Dear Mr. Else:

Please consider this as a reminder to attend the Ann Arbor Housing Board of Appeals meeting for your variance request. You will have the opportunity to address the Board regarding your request.

The meeting will take place on Tuesday, September 13, 2016 at 1:30 PM on the 2<sup>nd</sup> floor of City Hall in the Council Chambers. If you are planning to support your request with information or evidence not included with your application, please submit them to City Housing Department staff either by email at <a href="mailto:a2rentalhousing@a2gov.org">a2rentalhousing@a2gov.org</a> or in person no later than the Monday before the meeting to allow time for distribution to the Board members. If you bring additional materials to the meeting, please bring 10 hard copies for the Board members and City staff.

Sincerely,

Lisha Turner-Tolbert

Rental Housing Services Manager

James - Folbert