## **Adair Restoration LLC**



Adair Restoration LLC 1416 E. Stadium Blvd. Ann Arbor, MI 48104

(734)239-2886 radair77@yahoo.com

## **Estimate**

Date	Estimate #		
09/01/2011	1067		
	Exp. Date		

Total

\$8,450.00

## Address

Jim Curtis 343 S Main St Ann Arbor, MI 48104

A astroite.	Ougatitus	Doto	A
Activity	Quantity	Rate	Amount
• Remove plate glass from large windows on 2nd and 3rd floors. Replace with 3/4"	1	2,400.00	2,400.00
Low-E Tempered insulated glass units			
(6 total).		1 000 00	1 000 00
• Add 3/4" Low-E Tempered insulated glass units to exterior of smaller leaded glass windows on 2nd and 3rd floor (6 total)	1	1,800.00	1,800.00
• Apply aluminum to cover the exterior bottom rail and sill of window on 2nd and 3rd floors.	1	500.00	500.00
Materials: Large insulated glass units for 2nd and 3rd floors	6	400.00	2,400.00
Materials: Small insulated glass units for 2nd and 3rd floors	6	200.00	1,200.00
Materials: Aluminum, caulk, butyl tape, etc	1	150.00	150.00

I apologize for not getting this to you sooner, I've been busy with a new baby girl in my household. Please email or call with any questions.

Thanks for letting me quote your project,

Robin Adair

Accepted By: Accepted Date: