



U.S. Department
of Transportation
**Federal Aviation
Administration**

Air Traffic Organization
Central Service Center

2601 Meacham Blvd.
Fort Worth, TX 76137

AIRSPACE CASE NUMBER: 12-AGL-44NR

TO ALL INTERESTED PARTIES

PROPOSAL: The Federal Aviation Administration (FAA) has been advised by Mr. Paul Drobnik, Ypsilanti System Support Center at Belleville, Michigan, of his request to decommission the Detroit (DET) Outer Marker (OM) serving runway 15 at the Coleman A. Young Municipal Airport (KDET) in Detroit, Michigan. Federal Aviation Administration Flight Procedure Office has determined that there are no Instrument Flight Rules effects to this decommissioning. Should the study show that the decommissioning of the DET OM would not be detrimental to the NAS, the device will be removed without replacement.

The following effects are noted for DET OM decommissioning:

The ILS or LOC RWY 15 at KDET will have to be amended because the remaining NDB will require a new three letter identification and the five letter fix, MADDS will be cancelled and replaced.

PROPONENT: Paul Drobnik
Ypsilanti System Support Center
8808 Beck Rd.
Belleville, MI 48111

LOCATION: The physical component of this system is located:

Latitude: 42° 29' 41.39" N
Longitude: 083° 05' 36.07" W

This circularization is intended to provide the public with the opportunity to review and comment to the effect this proposal may have on aeronautical activity. The issuance of this non-rule circular is to give notice of impending action within the National airspace.


Comments regarding this proposal should be made in writing and directed to:

Federal Aviation Administration
ATO Central Service Center
Operations Support Group (AJV-C2)
Nonrulemaking Case No. 12-AGL-44NR
2601 Meacham Blvd.
Fort Worth, TX 76137

Comments received prior to March 28, 2013 will be considered before final action is taken on this proposal.

The specialist assigned to this study is Mr. Ron Laster, ron.ctr.laster@faa.gov, Support Specialist, Operations Support Group, ATO Central Service Center, telephone (817) 321-7741.

Issued in Fort Worth, TX, on **JAN 29 2013**



David P. Medina
Manager, Operations Support Group
ATO Central Service Center