ANN ARBOR HISTORIC DISTRICT COMMISSION

Staff Report

ADDRESS: 722 East Kingsley, Application Number HDC17-026

DISTRICT: Old Fourth Ward Historic District

REPORT DATE: March 9, 2017

OWNER

REPORT PREPARED BY: Jill Thacher, Historic Preservation Coordinator

REVIEW COMMITTEE DATE: Monday, March 6, 2017

Name:	Deinco Properties, LLC	Peter Deininger
Address:	318 E. Jefferson #6	2615 English Oak Dr.
	Ann Arbor, MI 48104	Ann Arbor, MI 48103
Phone:	(734) 323-6937	

BACKGROUND: This two-story house appears in the 1894 Polk Directory as #52 East Kingsley, the home of John W. Keating, Editor, Physician and Surgeon, and boarder Miss Mary A. Keating. The house is presumably older. In 1931, the house had a full-width front porch and a very large attached rear garage, which at some point was replaced with a single-story addition that is half as deep. Under the aluminum siding and vinyl shutters is presumably a simple Italianate home. The cut stone foundation and chamfered porch posts on the Thayer side are clues to its age and earlier appearance.

APPLICANT


LOCATION: The site is located on the southwest corner of East Kingsley and North Thayer Streets.

APPLICATION: The applicant seeks HDC approval to replace a vinyl double-hung with a casement window, replace a contributing wood double-hung with a casement window, and remove a fire escape, all on the west elevation.

APPLICABLE REGULATIONS:

From the Secretary of the Interior's Standards for Rehabilitation:

- (2) The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces, and spatial relationships that characterize a property will be avoided.
- (9) New additions, exterior alterations, or related new construction will not destroy historic



materials, features, and spatial relationships that characterize a property. The new work will be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.

From the Secretary of the Interior's Guidelines for Rehabilitating Historic Buildings:

Windows

<u>Recommended</u>: Designing and installing additional windows on rear or other non-character defining elevations if required by new use.

Identifying, retaining, and preserving windows--and their functional and decorative features-that are important in defining the overall historic character of the building.

<u>Not Recommended</u>: Removing or radically changing windows that are important in defining the historic character of the building so that, as a result, the character is diminished.

Introducing a new design that is incompatible with the historic character of the building.

District or Neighborhood Setting

<u>Not Recommended</u>: Introducing new construction into historic districts that is visually incompatible or that destroys historic relationships within the setting.

From the Ann Arbor Historic District Guidelines:

Windows

<u>Not Appropriate</u>: Introducing a new design that is incompatible with the historic character of the building.

STAFF FINDINGS:


- 1. The proposed work is on the west side elevation of the house, which is the arguably the least-visible side on this corner lot. The house has three units, an efficiency and two one-bedroom apartments, and a maximum total occupancy of six (two in each unit). The long-time owner wants to return the building to a single-family house with five bedrooms, still with a maximum occupancy of six. Once converted back to single family, it would stay that way under the current zoning ordinance. The lot is not large enough to allow the division of a single-family home.
- 2. One room on the first floor and one on the second that are not currently bedrooms require the installation of egress windows. Each has a double-hung that does not meet code requirements for clear opening size. The downstairs window is a modern vinyl replacement, but the upstairs window appears to be from the period of significance, based on photos and the owner's opinion. The applicant has worked with staff and the building official to minimize the number of windows required to be replaced and to find the least visible location for those.

- 3. The proposed replacement windows are Pella aluminum-clad wood casements with 2" applied horizontal muntins across the center designed to look like a meeting rail.
- 4. Removing the steel fire escape on the west elevation is appreciated and appropriate.
- 5. Staff feels that returning the home to single-family use is generally desirable and appreciates that the proposed floorplan, though not in the HDC's purview, is close to the original layout of the house. The work will be minimally visible from the public right of way, on the least character-defining side of the building. Removing the fire escape will be an immediate improvement in the appearance of the west elevation. Therefore, staff believes the proposal meets the Secretary of the Interior's Standards and Guidelines, and the Ann Arbor Historic District Design Guidelines and recommends approval.

POSSIBLE MOTIONS: (Note that the motion is only a suggestion. The Review Committee, consisting of staff and at least two Commissioners, will meet with the applicant on site and then make a recommendation at the meeting.)

I move that the Commission approve the application at 722 E. Kingsley, a contributing property in the Old Fourth Ward Historic District, to remove a vinyl first-floor window and a wood secondfloor window and replace them with the proposed clad wood casement windows, and remove a fire escape, all on the west elevation, on the condition that the fire escape is removed before the replacement windows' permits receive final approval. The work as conditioned is compatible in exterior design, arrangement, texture, material and relationship to the rest of the building and the surrounding area and meets *The Secretary of the Interior's Standards for Rehabilitation* and *Guidelines for Rehabilitating Historic Buildings,* in particular standards 2 and 9, and the guidelines for windows and neighborhood setting, and the *Ann Arbor Historic Guidelines* for windows.

ATTACHMENTS: application, photos, drawings, window information



722 E. Kingsley (2016 Google Streetview)

HDC17-026 2-17-17



City of Ann Arbor PLANNING & DEVELOPMENT SERVICES — PLANNING SERVICES

301 E. Huron Street | P.O. Box 8647 | Ann Arbor, Michigan 48107-8647 p. 734.794.6265 | f. 734.994.8312 | planning@a2gov.org

ANN ARBOR HISTORIC DISTRICT COMMISSION APPLICATION

Address of Property: 722 E. KINGSLEY
Historic District: OLD FOURTH WARD (OFW)
Name of Property Owner (If different than the applicant): DEINLO MORERTIES, LLC
Address of Property Owner: 318 E. JEFFERSON #6, A= 48104
Daytime Phone and E-mail of Property Owner: 734-323-6937 REFER DEININGER.
Signature of Property Owner:Date:D
Section 2: Applicant Information
Name of Applicant: PETER DEININGER
Name of Applicant: RETER DEININGER Address of Applicant: 2615 ENGLISH OAK DRIVE, AZ 48103
Address of Applicant: <u>615 ENGLISH OAK DICIVIL, M</u> 18703 Daytime Phone: <u>734, 996-1991</u> Fax:(
E-mail: KETERDEININGERCHOTMALL, LM
Applicant's Relationship to Property:ownerarchitectcontactorother
Signature of applicant:
Section 3: Building Use (check all that apply)
Section 3: Building Use (check all that apply) Section 3: Building Use (check all that apply)
Commercial Institutional
Section 4: Stille-DeRossett-Hale Single State Construction Code Act (This item MUST BE INITIALED for your application to be PROCESSED)
Public Act 169, Michigan's Local Historic Districts Act, was amended April 2004 to include the following language: "the applicant has certified in the application that the property where the work will be undertaken has, or will have before the proposed completion date, a a fire alarm or smoke alarm complying with the requirements of the Stille-DeRossett-Hale Single State Construction Code Act, 1972 PA 230, MCL 125.1501 to 125.1531."



Section 5: Description of Proposed Changes (attach additional sheets as necessary) 1. Provide a brief summary of proposed changes. PROPER BUILDING CODE EPLACE TWO WINDOWS FOR ONE ON FIRST FLOOR WHICH IS VINYL LSS. NOT ORIGINAL AND ONE ON THE SECOND FLOOR WHICH IS ORIGINAL TO THE HOUSE . ALSO EXISTING ESCA 2. Provide a description of existing conditions. TWO WINDOWS CURRENTLY DONBLE MEST DO NOT PROVIDE THE ROPER EGRESS AND REQUIRED FOR BEDROOMS UNDER THE IS KULDING CODE. 3. What are the reasons for the proposed changes? THE HOUSIE IS BEING CONVERTED FROM THREE UNIT APARTMENT HOUSE BALK TO SINGLIE FAMILY. 4. Attach any additional information that will further explain or clarify the proposal, and indicate these attachments here. ARCMITECT DRAWINGS. MORTOACE SURVIEY. HELLA WINDOW DETAIL, EXISTING TWO WINDOW PICTURES. 5. Attach photographs of the existing property, including at least one general photo and detailed photos of proposed work area. STAFF USE ONLY Date Submitted: Application to _____Staff or _____HDC Fee Paid: Project No.: ____ HDC____ Pre-filing Staff Reviewer & Date: _____ Date of Public Hearing: _____ Application Filing Date: _____ Action: _____ HDC COA _____ HDC Denial _____HDC NTP _____ Staff COA Staff signature: Comments:

150.00 150.00 150.00
150.00

여 다.

. 1ª H

18.14

. 18.18

19.11

-'na (†

ंग सु



------ST FLOOR











EXTERIOR VIEWS / 722 E. Kingsley

Proposed Interior Renovations at: 722 E. KINGGLEY ANN ARBOR M DEINCO PROPERTIES

> 1 - 30 - 17 1 - 18 - 17 11 - 9 - 16 10 - 11 - 16

A-4



Seals tight and locks easily.

Architect Series* casement windows feature the SureLock* System that reaches out to pull the window sash against the weatherstripping to form a tight seal against drafts, making them more energy-efficient. Plus, Pella's patented Unison Lock System secures casement and awning windows in two places with a single, easy-to-reach handle.



Lasting beauty.

CONTEMPORARY

EnduraGuard[®] wood protection offers advanced protection against the effects of moisture, decay, stains from mold and mildew – as well as termite damage. This proven immersion-treatment method will help ensure that Pella[®] wood windows and patio doors look and perform beautifully for years.



Pella's casement window after 7 months of exposure to moisture.*





Stain mold present after 7 months of field-testing a competitor's pressure-treated wood.*



The confidence of added protection.

Pella products are backed by some of the strongest warranties in the business. See written limited warranty for details, including exceptions and limitations, at pella.com/warranty.






Ann Arbor, MI 48104 EdWier@aol.com

A - 1

Edwin R. Wier ARCHITECT Ann Arbor, MI 48104 EdWier@ao! com 1503 Shadford Rd. Tele: 734-761-3015


DEINCO PROPERTIES

A-1



1

FIRST FLOOR PLAN (Existing) SCALE: 14"=1-0"



SCALE: 1/4" = 1- 0"



ŝ

3112

O+ D CLOBER S

BEDROOM #5 4-10" x 11'-1" (EVS~G)

Bestie

7

CLOSE

п

5

9/9 C

ŝ

NODWN

Evang wedow

EX675

00

BATH (march)

BEDROOM #4

20102

ENSTG WINCOW

SSBCG VINCOVIN

OLCOST

6.6

r-5 1

20.00)

2.0

VERFY WALL LOCATION FOR STAR CLEARANCE / REWORK AS REQU

..... 1

SECOND FLOOR PLAN (Revised)

E ENETS ENETS

BEDROOM #3

NOC/1N

HADED - YF)

EXISTIG (VALL) JICHEN REMOVED (SHOWN DASHED)


PER 20'S MICHGAN RESDENTIA_ CODE ("IN, 5." SQ. TI, NE" C_BAR OPING W/ MAX 44' BLL HT. AND MN, 20' WDTH AND 24' -1'.)

PELLA 2559 (EGREGE) CASEMENT (V. SMULATER D.-, CHECK RAL (SR APPROVED EQUAL) VERFY SIZE (N. FELD

DEINCO PROPERTIES

Proposed Interior Renovations at: 722 E. KINGSLEY ANN ARBOR. MI DEINCO PRO






SECOND FLOOR PLAN (Existing) SCALE: 1/4" = 1- 0"

Edwin R. Witer A R C HITE C T 1903 Shadrof Ra Ann Arbor, M. 48104 Tele: 734-761-3015 Edwine@ad.com

DEINCO-PROPERTIES Proposed Interior Renovations at: 722 E. KINGSLEY ANN AREAR MI DENCORCO

1 - 30 - 17 1 - 18 - 17 11 - 9 - 16 10 - 11 - 16 A-3



BASEMENT PLAN


Certified to: DEINCO PROPERTIES, LLC.

Property Description:

The East 43.17 feet of Lot 5, Block 4 North, Range 10 East; LAWRENCE AND MAYNARDS ADDITION, to the City of Ann Arbor, Washtenaw County, Michigan, as recorded in Liber 27 of Plats, Page 471 of Washtenaw County Records.

NOTE: A BOUNDARY SURVEY IS NEEDED TO DETERMINE EXACT SIZE AND/OR LOCATION OF PROPERTY LINES. NOTE: A COMPLETE CURRENT TITLE POLICY HAS NOT BEEN FURNISHED, THEREFORE EASEMENTS OR OTHER ENCUMBRANCES MAY NOT BE SHOWN AT THIS TIME.







Contract - Detailed

Carter Lumber #0248 46401 Erb Dr Macomb, MI 48042 Phone: (586) 913-8700 Fax: (586) 913-8786

Sales Rep Name: Boerner, John Sales Rep Phone: 586-913-8730 Sales Rep Fax: Sales Rep E-Mail: jboerner@carterlumber.com

Customer Information	Project/Delivery Address	Order Informa	Order Information		
The Carter Companies - 00248	DENICO PROPERTIES -dan snyder	Quote Name:	Quote Name: Unassigned		
00000 THE CARTER COMPANIES	00248 THE CARTER COMPANIES				
601 Tallmadge Road	46401 Erb Dr	Order Number:	P79		
KENT, OH 44240	Lot #	Quote Number:	8667349		
Primary Phone: (586) 9138700	MACOMB, MI 48042-5313	Order Type:	Non-Installed Sales		
Mobile Phone:	County: MACOMB	Wall Depth:			
Fax Number: (586) 9138786	Owner Name:	Payment Terms:	C.O.D.		
E-Mail:	The Carter Companies - 00248	Tax Code:	6.0 %		
Contact Name:	Owner Phone: (586) 9138700	Cust Delivery Date	03/02/2017		
		Quoted Date:	2/9/2017		
Great Plains #: 7900248		Contracted Date:			
Customer Number:		Booked Date:			
Customer Account:		Customer PO #:			

Line # Location: 10 None Assigned **Item Price** Ext'd Price Architect, Casement Left, 29 X 47, White Qty \$433.53 \$433.53 1 1: 2947 Left Casement Frame Size: 29 X 47 General Information: Standard, Clad, Pine, 5", 3 11/16" PK# Exterior Color / Finish: Painted, Standard Enduraciad, White Interior Color / Finish: Unfinished Interior 1978 Sash / Panel: Ogee, Ogee, Standard Glass: Insulated Dual Low-E NaturalSun Low-E Insulating Glass Argon Non High Altitude Hardware Options: Wash Hinge Hardware, Fold-Away Crank, White, No Window Opening Control Device, No Limited Opening Hardware Viewed From Exterior Screen: Full Screen, White, InView™ Performance Information: U-Factor 0.31, SHGC 0.39, VLT 0.44, CPD PEL-N-11-10956-00002, Performance Class CW, PG 50, Calculated Positive DP Performance information: O-Factor 0.31, SH6200, 0.39, VET 0.44, CPD PEL-N-11-10950-00002, Pendinance class CW, PG 50, Calculated Positive D Rating 50, Calculated Negative DP Rating 50, Year Rated 08 Grille: ILT, No Custom Grille, 2", Traditional (1W2H), Ogee, Ogee Wrapping Information: Foldout Fins, Factory Applied, No Exterior Trim, No Interior Trim, 4 9/16", 5 7/8", Standard Four Sided Jamb Extension, Factory Applied, Pella Recommended Clearance, Perimeter Length = 152". Overall Rough Opening Dimensions: 29 3/4 X 47 3/4 Rough Opening: 29 - 3/4" X 47 - 3/4"

 For more information regarding the finishing, maintenance, service and warranty of all Pella® products, visit the Pella® website at www.pella.com
 Image: Contract - Detailed
 Page
 1
 of
 4

 Printed on 2/9/2017
 Contract - Detailed
 Page
 1
 of
 4

lipstairs

Line #	Location:	Attributes	- A.			
15	5 None Assigned	Architect, Casement Left, 25 X 59, White		Item Price	Qty	Ext'd Price
Viewe	PK# 1978 Viewed From Exterior	1: 2559 Left Casement Frame Size: 25 X 59 General Information: Standard, Clad, Pine, 5", 3 11/16" Exterior Color / Finish: Painted, Standard Enduraclad, White Interior Color / Finish: Unfinished Interior Sash / Panel: Ogee, Ogee, Standard Glass: Insulated Dual Low-E NaturalSun Low-E Insulating Glass Argon Non High Alti Hardware Options: Side Pivot Hardware, Fold-Away Crank, White, No Window Open		\$513.28 ited Opening Hard	1 ware	\$513.2
		Screen: Full Screen, White, InView™ Performance Information: U-Factor 0.31, SHGC 0.39, VLT 0.44, CPD PEL-N-11-10 Rating 45, Calculated Negative DP Rating 45, Year Rated 08 Grille: ILT, No Custom Grille, 2", Traditional (1W2H), Ogee, Ogee	956-00002, Performance C	lass CW, PG 45, 0	Calculated	Positive DP

Rough Opening: 25 - 3/4" X 59 - 3/4"

For more information regarding the finishing, maintenance, service and warranty of all Pella® products, visit the Pella® website at www.pella.com
Printed on 2/9/2017 Contract - Detailed Page 2 of 4

Downstants


UNIT SECTIONS - WOOD COLLECTION


Aluminum-Clad Wood



Alder or Douglas Fir Interior


CASEMENT






Solid Pine


Pine or Mahogany Interior








Solid Mahogany or Pine


Not to Scale













VERTICAL JOINING MULLION VENT / VENT




HORIZONTAL JOINING MULLION TRANSOM / VENT




VERTICAL JOINING MULLION VENT / FIXED

Scale 3" = 1' 0" All dimensions are approximate.



See Installation and Performance at www.PellaADM.com for mullion limitations and reinforcing requirements.



Typical Grille Profiles

GRILLE TYPES


Designer Series®


ProLine 450 Series


CASEMENT














Putty Glaze and Ogee Grilles Clad Exterior - Wood Interior,






Roomside Removable Grilles



3/4" Regular


Grilles-Between-the-Glass





7/8





2" Regular
















Putty Glaze and Ogee Grilles Wood Exterior - Wood Interior₂


















2" Colonial

(1) Available in Pine, Mahogany, Alder or Douglas Fir to match complete unit.

(2) Available in Pine or Mahogany to match complete unit.