### ANN ARBOR HISTORIC DISTRICT COMMISSION

### Staff Report

ADDRESS: 613-619 E William Street and 342 S State, Application Number HDC19-168

**DISTRICT:** State Street Historic District

**REPORT DATE:** September 12, 2019

**REPORT PREPARED BY:** Jill Thacher, Historic Preservation Coordinator

**REVIEW COMMITTEE DATE:** Monday, September 9, 2019

	OWNER	APPLICANT
Name:	West Second Street Associates	OX Studio, Inc
Address:	503 S Saginaw St, Suite 600	2373 Oak Valley Dr, Suite 180
	Flint, MI 48502	Ann Arbor, MI 48103
Phone:	(810) 239-1551 x312	(734) 828-1856

**BACKGROUND:** This two-story commercial block It features metal siding over brick construction, with a tin cornice and tin detailing. The bay at 619 was built first, in 1892, and the first occupant was Lewis Stevens barber and baths. Vertical tin siding is visible on the second floor. The diamonds above the window also appear to be older and more substantial than the ones on the other storefronts to the west. 613-617\* was built in 1899 and the original occupant was shoemaker Eugene Lambert. The three-story building to the east at 342 S State was built in 1905. Current occupants of 613-619 are Tianchu Restaurant and Pita Kabob Grill.

\*Please note that there is a discrepancy in the building addresses of the Downtown Survey, which groups 613 and 617 as one building and 619 as another. Physical and photographic evidence suggests 613 was added later to the 617-619 building.

The current storefronts on the first floor are entirely non-original, with the exception of the cornice band detailing above the storefront windows of 619, and one original iron column.

**LOCATION:** The building is located on the north side of East William Street, one building west of South State.

**APPLICATION:** The applicant seeks HDC approval to install new storefronts along the extent of the two-story building and replace a side door facing E William on 342 S State, in the existing opening.

### **APPLICABLE REGULATIONS:**

### From the Secretary of the Interior's Standards for Rehabilitation:

(1) A property will be used as it was historically or be given a new use that requires minimal change to its distinctive materials, features, spaces, and spatial relationships.

- (2) The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces, and spatial relationships that characterize a property will be avoided.
- (9) New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.

## From the Secretary of the Interior's Guidelines for Rehabilitating Historic Buildings (other SOI Guidelines may also apply):

### Storefronts

<u>Recommended</u>: Designing and constructing a new storefront when the historic storefront is completely missing. It may be an accurate restoration using historical, pictorial, and physical documentation; or be a new design that is compatible with the size, scale, material, and color of the historic building.

<u>Not Recommended</u>: Introducing a new design that is incompatible in size, scale, material, and color.

### **Building Site**

<u>Not Recommended</u>: Removing or radically changing buildings and their features or site features which are important in defining the overall historic character of the property so that, as a result, the character is diminished.

### Windows

<u>Recommended</u>: Designing and installing new windows when the historic windows (frames, sash and glazing) are completely missing. The replacement windows may be an accurate restoration using historical, pictorial, and physical documentation; or be a new design that is compatible with the window openings and the historic character of the building.

<u>Not Recommended</u>: Introducing a new design that is incompatible with the historic character of the building.

### From the Ann Arbor Historic District Design Guidelines:

### **Design Guidelines for Storefronts**

<u>Appropriate</u>: Designing and constructing a new storefront when the historic storefront is completely missing. It may be an accurate restoration using historical, pictorial, ad physical documentation; or may be a new design that is compatible with the size, scale, and material of the historic building. New designs should be flush with the façade and be kept as simple as possible.

<u>Not Appropriate</u>: Installing a new storefront that is incompatible in size and material with the historic building and district.

### Signs

<u>Appropriate:</u> Installing signage in the historic sign band area of the building, typically the area above the transoms or just above the storefront.

Installing signage that is compatible in size, style, material, and appearance to the historic resource and district.

Placing signs to align with others along the commercial block face.

Installing signage that is subordinate to the overall building composition.

### Windows

<u>Appropriate:</u> If a window is completely missing, replacing it with a new window based on accurate documentation of the original or a new design compatible with the original opening and the historic character of the building. Materials other than wood will be reviewed by the Commission on a case-by-case basis.

### **STAFF FINDINGS:**

- 1. The storefront in 619 was approved by the HDC in 2001. The original design, with a recessed double entry in the center of 617 and 619, is not reproduceable because of interior changes to the original layout. The proposed storefronts carry the first floor cornice trim from 619 through 617, and retain the basic proportions and large pieces of glass seen in photographs from the 1940s. The cornice on 613 is simplified, since historic documentation of what it originally looked like does not exist. The element most obviously missing is the transom window originally found on 617-619.
- 2. A sign band is being shown where the transoms would historically go above the new storefronts. Signage is shown on the plans and staff asks that the applicant submit dimensions of those sign areas (three wall signs and three pedestrian scaled bracket signs). If approved by the HDC, this will allow staff to approve future signage that does not exceed those dimensions, in the same locations. Any other signage must be approved by the HDC instead of staff.
- 3. The signs show gooseneck lighting with a 12 5/8" diameter shade. The HDC's policy has been to not allow new gooseneck lights, and staff can only recall one in recent history (an exception was made for Salads Up). The fixtures proposed here are more modern than a traditional barn light, but staff's opinion is that they are still goosenecks. Elevation drawings A101-102 show two goosenecks per each of the three signs, plus one on the westernmost pedestrian scale sign. The color images are inconsistent in the number and placement of lights, but staff defaults to what is shown on the elevations. Since there are streetlights in front of 619 and 611 E William (across the alley to the west), staff has concerns that the lights will be overkill. If the HDC believes the fixtures are appropriate, the suggested motion is conditioned on limiting the lighting to two fixtures on the signs at 613 and 619, one on 617, and none on the two bracket signs.
- 4. Despite some smallish concerns, staff finds that the redesign of the storefront is a vast improvement over the existing mishmash and is generally appropriate and meets

the Secretary of the Interior's Standards and Guidelines, and the Ann Arbor Historic District Design Guidelines.

**POSSIBLE MOTIONS:** (Note that the motion is only a suggestion. The Review Committee, consisting of staff and at least two Commissioners, will meet with the applicant on site and then make a recommendation at the meeting.)

I move that the Commission issue a certificate of appropriateness for the application at 613-619 E William Street, a contributing property in the East William Historic District to install new storefronts along the extent of the two-story building, and replace a side door facing East William Street on 342 S State, in the existing opening, on the following condition: that sign lighting is limited to: two fixtures on the signs on 613 and 619, one on 617, and none on the two bracket signs. The work as conditioned is compatible in exterior design, arrangement, texture, material and relationship to the rest of the building and the surrounding area and meets the *Ann Arbor Historic District Design Guidelines* for storefronts, windows, and signs, and *The Secretary of the Interior's Standards for Rehabilitation* and *Guidelines for Rehabilitating Historic Buildings,* in particular standards 1, 2, and 9 and the guidelines for storefronts, windows, and building site.

### **MOTION WORKSHEET:**

I move that the Commission issue a Certificate of Appropriateness for the work at <u>309 S. Main</u> <u>Street</u> in the <u>Main Street</u> Historic District

\_\_\_\_\_ Provided the following condition(S) is (ARE) met: 1) STATE CONDITION(s)

The work is generally compatible with the size, scale, massing, and materials and meets the Secretary of the Interior's Standards for Rehabilitation, standard(S) number(S) *(circle all that apply)*: 1, 2, 3, 4, 5, 6, 7, 8, 9, 10

### ATTACHMENTS: Application, photos, drawings

### Photos

617 and 619 E William, 1946 (courtesy AADL Old News)



F-6 (p. 5)



617-619 E William, Varsity Barbershop picket, 1947 (courtesy AADL Old News)

613 E William, 1973 (courtesy AADL Old News)



### 613-617-619 E William, 1974 (courtesy AADL Old News)



617-619 E William, 1979 (courtesy AADL Old News)



### HISTORIC DISTRICT COMMISSION



### PLANNING AND DEVELOPMENT SERVICES

 City Hall:
 301 E. Huron St. Ann Arbor, MI 48104-6120

 Mailing:
 P.O. Box 8647, Ann Arbor, MI 48107-8647

 Phone:
 734.794.6265 ext. 42608

 Fax:
 734.994.8460

	OFFICE USE ONLY
Permit Number	HDC#
r ennit Number	BLDG#
	DATE STAMP

### APPLICATION MUST BE FILLED OUT COMPLETELY

PROPERTY LOCATIO	ON/OWNER INFORMATION		HISTORIC DISTRICT	
The second second states when the second	ond Street Associates, Troy Fa	arah	State Street	
PROPERTY ADDRESS				CITY
613-619 Wi	lliams			ANN ARBOR
zipcode 48104	DAYTIME PHONE NUMBER	EMAIL ADDRESS		
	810-239-1551 X312	tfarah@wssallc.com		
	dress (if different from above) aw St. Suite 600		Flint	STATE, ZIP 48502
PROPERTY OWNER				19 JUS - 19 St.
SIGN HERE	NY	PRINT NAME TROY	FRRAH	DATE 8 22/1
APPLICANT INFORM	<b>NATION</b>			
	DIFFERENT FROM ABOVE)			
UX STUDIO, ADDRESS OF APPLICANT	Inc., Anna Epperson			СІТУ
2373 Oak V	alley Dr. Suite 180			Ann Arbor
STATE	ZIPCODE	PHONE / CELL #	FAX No	
MI and an	48103	( 734 ) 828-1	856 (	)
EMAIL ADDRESS	e@oxstudioinc.com			
APPLICANT'S SIGNA	ATURE (if different from Property O	vner)		
SIGN HERE	La Mor	ргілт маме x Аппа Ерр	person	DATE 08/22/2019
BUILDING LISE - CH	IECK ALL THAT APPLY	States and the second second	N NUMBER OF STREET	
SINGLE FAMILY				
PROPOSED WORK				
PROPOSED WORK	ach proposed exterior alteration, imp	rovement and/or renair (use addit	tional naner if necessary)	
	en proposed exterior diteration, imp	rovement unity of repair (use uture	ional paper, ij necessary).	
See attach	ied			
DESCRIBE CONDITIC	ONS THAT JUSTIFY THE PROPOSED O	HANGES.		
See attach	ied			÷
	5 - 10 - 10 - 10 - 10 - 10 - 10 - 10 - 1			
For Further Assistance	With Required Attachments, please visit	www.a2gov.org/hdc		

G:\Community Services\CSA Shared\Planning & Development\Permit Application Forms



### HISTORIC DISTRICT COMMISSION APPLICATION

FEE CHART	
DESCRIPTION	
STAFF REVIEW FEES	FEE
Application for Staff Approval	\$35.00
Work started without approvals	Additional \$50.00
HISTORIC DISTRICT COMMISSION FEES	
All other proposed work not listed below	\$100.00
Work started without approvals	Additional \$250.00
<b>RESIDENTIAL – Single and 2-story Structure</b>	
Addition: single story	\$300.00
Addition: taller than single story	\$550.00
New Structure - Accessory	\$100.00
New Structure – Principal	\$850.00
Replacement of single and 2-family window(s)	\$100 + \$25/window
COMMERCIAL – includes multi-family (3 or structures	more unit)
Additions	\$700.00
Replacement of multi-family and commercial window (s)	\$100 + \$50/window
Replacement of commercial storefront	\$250.00
DEMOLITION and RELOCATION	
Demolition of a contributing structure	\$1000.0
Demolition of a non-contributing structure	\$250.00
Relocation of a contributing structure	\$750.00
Relocation of a non-contributing structure	\$250.00

FOR COMMISSION REVIEWS:

- Application withdrawals made before public notice is published will qualify for a 50% refund of the application fee.
- Application withdrawals made after public notice is sent but before the public hearing will qualify for a 25% refund of the application fee.

### INSTRUCTIONS FOR SUBMITTING APPLICATIONS

All HDC applications must be signed by the property owner and the applicant, if different, with the exception of staff approvals, which may be signed by only the applicant.

All completed HDC applications and their attachments may be submitted to Planning and Development Services by mail, in person (paper or digital), faxed, or via email to <u>building@a2gov.org</u>.

We accept CASH, CHECK, and all major credit cards. Checks should be made payable to "City of Ann Arbor"

HDC applications that are incomplete or not submitted with the required documentation or payment will not be processed or approved.

### APPLICATION EXPIRATION

HDC applications expire three (3) years after the date of approval.

OFFICE USE ONLY		
Date of Hearing:		
Action	□ HDC COA	HDC Denial
Action	□ HDC NTP	□ Staff COA
Staff Signature		
Comments		
Fee:	\$	
Payment Type	<ul> <li>Check: #</li> <li>Cash</li> <li>Credit Card</li> </ul>	

August 23, 2019

Ann Arbor Historic District Commission Planning and Development Services 301 E. Huron St. Ann Arbor, MI 48104



RE: State & William Historic Façade Improvements, O|X Project SWF19 Historic District Commission Review

Dear Commissioners,

This property is located at a key intersection in downtown Ann Arbor, directly on the corner of State and William Streets. This location is directly across from the University of Michigan Diag. The site is bounded by properties of varying use and scale, including a historic Greek Life building, a church and adjacent commercial properties. A small 12' wide easement is provided at the western end of the property for a public alley. The buildings are presently owned and maintained as a collective whole by the Owner.

The physical buildings vary in overall size, height, construction typology and exterior finishes. The 342 building is a three-story structure with lower level retail and upper level office space. The primary building façade is brick masonry with a contemporary marble/stone veneer cladding and anodized aluminum storefronts at the base level. The upper levels are contemporary replacement windows in punched openings along with historical bay windows. The building is capped by an ornate metal cornice along State and William streets. The William Street buildings are two-stories in height and are combination of underlying masonry façade with contemporary wood cladding and embellishments composed in a haphazard fashion. A small portion of historically significant corrugated metal siding remains on the second story, along with decorative diamond shapes and a metal cornice with corbels. A small portion of the original storefront cornice along with a single cast iron column, remains on the first floor. The floor levels vary between the two primary structures. Mechanical units for the tenants are located on the roof along with various projecting air conditioning units.

This portion of the work is part of a larger building renovation effort by the Owner to improve the physical conditions of the building. Other work to be carried out concurrently and already reviewed by Ann Arbor HDC staff includes restoration of existing cornice work, masonry tuckpointing and masonry unit repair, and re-painting of previously painted brick facades. Mechanical and plumbing on the primary facades will be removed and re-routed to improve the overall appearance of the building.

The work proposed includes the replacement of the building façade and storefront materials on the first level of 613-619 E. William Street. A small portion of storefront is also proposed to be replaced along William street on the 342 S. State Street building address.

www.oxstudioinc.com

OID STUDIO

Work proposed will re-establish the 613-619 William Street facades as two distinct buildings. The storefronts will be rebuilt to similar proportions of the original and previous façade designs based on historic imagery. The remaining historic remnants of the storefront cornice of 619 William, along with the remaining cast-iron column will be restored. A new replicated storefront cornice will be installed adjacent to the existing cornice to extend the full length of the 619 façade. Due to modern updates, including structural columns, and current tenant occupancies, reconfiguring the storefront to match exact proportions is not possible. The adjoining 613 façade will be rebuilt in similar proportions and materials while remaining distinct from the 619 façade. No original historic imagery was found for 613 William, as such, the proposed proportions and surface treatment are intentionally simplified and established to compliment the 619 façade.


Sincerely,

Anna Epperson Architectural Designer O|X Studio, Inc.





















619 E. William St. Historic Facade Imagery, c. 1973








613 E. William St. Historic Facade Imagery, c. 1973





**Existing Facade Conditions** 






**Existing Facade Conditions** 












Existing Facade Conditions













Existing Facade Conditions, remaining level 1 historic elements



# State & William

613 E. William, Ann Arbor, MI 48104

### Released For: HDC Review

Release Date: 08/23/2019 OX Project Number: WSS-SWF19

### Project Team

### Owner: West Second Street Associates Contact: Lynae Davis 503 S. Saginaw St. Suite 600 Flint, MI 48502 810-239-1551 x303 Idanias@wssallc.com

Architect: O X Studio, Inc. Contact: Robb Burroughs 302 S. State St., Suite B, Ann Arbor, MI 48104 (734) 929-9000 . Robb@oxstudioinc.com

### General Contractor: TBD

Contact: Name Address Phone Email

Email

#### Historic Restoration TBD Contractor: Address Phone

Contact: Name

### Project Description

#### This project is a storefront renovation within the State Street Historic District in Ann Arbor Michigan. The new storefront will be rebuilt within the same plane as the existing storefront. Tenant egress locations will remain in their existing locations. New openings and new facade materials will be installed, arranged in a manner that meets the City of Ann Arbor Historic District Design Guidelines. Limited electrical work will be completed to remove and relocate lighting.




3	I	2	1			abjects nc.cam
				× _ J		architecture   construction   objects P. (734) 929-9000   F. (734) 929-9001   www.oxstudioinc.com
				н 	-	
ime	Current Revisior	n Description	Current Revis Date	F ion E	State & William	E. William, Ann Arbor, MI 48104
	HDC Review		08/23/2019		Sheet Title:	E13
	HDC Review HDC Review HDC Review HDC Review HDC Review		08/23/2019 08/23/2019 08/23/2019 08/23/2019 08/23/2019		Title Sheet	Released For: HDC Review
				B	08/23/20 wss-sw G-10	F19 #1
	<u> </u>	HDC Review HDC Review HDC Review HDC Review HDC Review HDC Review HDC Review	HDC Review HDC Review HDC Review HDC Review HDC Review HDC Review HDC Review	ame         Current Revision Description         Date           HDC Review         08/23/2019           HDC Review         08/23/2019	HDC Review       08/23/2019         HDC Review       08/23/2019	Image: Current Revision Description       Current Revision Description         Image: Current Revision Description       Date         Image: Curr


5		3   2		Restriction objects	erchitecture   construction   agreeds P: (734) 929-9000   F: (734) 929-9001   www.oxstudioinc.com
Draw Sheet Number General G-100	ITITIE Sheet	Current Revision Descrip	otion Current Revision Date 08/23/2019	G Job Title: F State & Milliam	613 E. William, Ann Arbor, MI 48104
Demolition AD-101 Architectu A-100 A-101 A-102 A-103 A-104	Demolition Plan	HDC Review HDC Review HDC Review HDC Review HDC Review HDC Review	08/23/2019 08/23/2019 08/23/2019 08/23/2019 08/23/2019 08/23/2019 08/23/2019	Sheet Title:	Released For: HDC Review
				B 08/23/201 WSS-SWF1	+

NOT FOR CONSTRUCTION







CONSTRUCTION




File Path: C:\Revit Local Files\SWF19 8/23/2019 1:12:04 PM









### **General Sheet Notes:**

- A. Existing wood framed wall construction to remain.
- B. Exisiting cavity insulation to remain. Infill with similar insulation as required.

### Basis of Design:

Storefront System: Tubelite 14000 Series Front glazed system with 2"x4 1/2" Frame profile, 2" mullions, Anodized black finish. Provide Head receptor and Sill with flashing and integral end dam. Storefront Entrance Doors: Tubelite Narrow Stile Glazing: 1" Insulated glazing unit: Guardian Glass; SNX 62/27:


Outboard Lite: Annealed float glass, 1/4 inch thick, minimum.

Tint: Clear, Low-Iron. Coating: Low-E (passive type), on #2 surface Inboard Lite: Annealed float glass, 1/4 inch thick, minimum. Tint: Clear.

Thermal Transmittance (U-Value), Summer - Center of Glass: 0.27. Visible Light Transmittance (VLT): 64 percent, nominal. Solar Heat Gain Coefficient (SHGC): 27 percent, nominal.

Light Fixture: Bega 66411 LED wall luminaire, partially shielded, black, 3500K





### **General Sheet Notes:**

- A. Existing wood framed wall construction to remain.B. Exisiting cavity insulation to remain. Infill with similar insulation as required.

### Basis of Design:

<u>Storefront System:</u> Tubelite 14000 Series Front glazed system with 2"x4 1/2" Frame profile, 2" mullions, Anodized black finish. Provide Head receptor and Sill with flashing and integral end dam. Storefront Entrance Doors: Tubelite Narrow Stile Glazing: 1" Insulated glazing unit: Guardian Glass; SNX 62/27:

Outboard Lite: Annealed float glass, 1/4 inch thick, minimum.

Tint: Clear, Low-Iron. Coating: Low-E (passive type), on #2 surface Inboard Lite: Annealed float glass, 1/4 inch thick, minimum. Tint: Clear.

Thermal Transmittance (U-Value), Summer - Center of Glass: 0.27. Visible Light Transmittance (VLT): 64 percent, nominal. Solar Heat Gain Coefficient (SHGC): 27 percent, nominal.

Light Fixture: Bega 66411 LED wall luminaire, partially shielded, black, 3500K







SWF19 State & William Facade Perspective

East View









August 23 2019 2







August 23 2019

### Application

This LED wall luminaire has a partially shielded light source and is designed for the down lighting of interior and exterior locations with glare-free illumination.

### Materials

Luminaire housing constructed of die-cast and spun marine grade, copper free ( $\leq 0.3\%$  copper content) A360.0 aluminum alloy Three-ply opal glass

High temperature silicone gasket

NRTL listed to North American Standards, suitable for wet locations Protection class IP 44 Weight: 4.0lbs

### Electrical

Operating voltage	120-277VAC
Minimum start temperature	-20° C
LED module wattage	8.9W
System wattage	12 W
Controllability	0-10V dimmable
Color rendering index	Ra > 90
Luminaire lumens	724 lumens (3000K)
Lifetime at Ta = 15° C	500,000 h (L70)
Lifetime at Ta = 40° C	268,000 h (L70)

LED color temperature

4000K - Product number + K4
3500K - Product number + K35
3000K - Product number + K3
2700K - Product number + K27

**BEGA** can supply you with suitable LED replacement modules for up to 20 years after the purchase of LED luminaires - see website for details

### Finish

All BEGA standard finishes are matte, textured polyester powder coat with minimum 3 mil thickness.

Available colors	Black (BLK)	White (WHT)	RAL:
	Bronze (BRZ)	Silver (SLV)	CUS:

Type: BEGA Product: Project: Modified:



LED wall luminaire · partially shielded						
	LED	А	В	С	D	
66411	8.9W	12 1/8	$14\frac{1}{2}$	131/2	4 3/8	



BEGA 1000 BEGA Way, Carpinteria, CA 93013 (805) 684-0533 info@bega-us.com

Due to the dynamic nature of lighting products and the associated technologies, luminaire data on this sheet is subject to change at the discretion of BEGA North America. For the most current technical data, please refer to bega-us.com © copyright BEGA 2018 Updated 08/14/18

# BEGA

Photometric Filename: 66411.IES

TEST: TEST LAB: DATE: LUMINAIRE: LAMP: ame: 66411.


BE 66411

BEGA 9/12/2017

66 411

8.9W LED





### **Characteristics**


IES Classification	Туре
Longitudinal Classification	Very
Lumens Per Lamp	N.A.
Total Lamp Lumens	N.A.
Luminaire Lumens	724
Downward Total Efficiency	N.A.
Total Luminaire Efficiency	N.A.
Luminaire Efficacy Rating (LER)	60
Total Luminaire Watts	12
Ballast Factor	1.00
Upward Waste Light Ratio	0.02
Max. Cd.	182.
Max. Cd. (<90 Vert.)	182.
Max. Cd. (At 90 Deg. Vert.)	21.8
Max. Cd. (80 to <90 Deg. Vert.)	47.4
Cutoff Classification (deprecated)	N.A.


Type V Very Short N.A. (absolute) 724 N.A. N.A. 60 12 1.00 0.02 182.007 (0H, 15V) 182.007 (0H, 15V) 182.007 (0H, 15V) 21.828 (3.0%Lum) 47.401 (6.5%Lum) N.A. (absolute)

### Lum. Classification System (LCS)

LCS Zone	Lumens	%Lamp	%Lum
FL (0-30)	75.5	N.A.	10.4
FM (30-60)	174.4	N.A.	24.1
FH (60-80)	85.8	N.A.	11.8
FVH (80-90)	18.4	N.A.	2.5
BL (0-30)	75.5	N.A.	10.4
BM (30-60)	174.4	N.A.	24.1
BH (60-80)	85.8	N.A.	11.8
BVH (80-90)	18.4	N.A.	2.5
UL (90-100)	14.5	N.A.	2.0
<u>UH (100-180)</u>	1.9	N.A.	0.3
Total	724.6	N.A.	100.0

BUG Rating B0-U2-G1





In the interest of product improvement, BEGA reserves the right to make technical changes without notice. **BEGA** 1000 Bega Way, Carpinteria, CA 93013 (805)684-0533 Fax (805)566-9474 www.bega-us.com © Copyright BEGA-US 2015