

Ann Arbor Crash Review Team Report

September 2025

Location: Jackson Ave. Near Worden

Crash Summary

UD-10 Number:	Unknown	AAPD Case Number:	25-48303
Date:	9/21/2025	Time:	12:54am
Number of Involved Units/Parties:	1	Highest Injury Level:	Fatality
Roadway Conditions:	Dry Asphalt, Downhill grade approaching then level at impact		
Weather Conditions:	Clear/Dry	Lighting Conditions:	Dark- Lighted
Contributing Factors/Description: Speed			
Crash Description: A motorcyclist was driving eastbound on Jackson Ave at a high rate of speed (video analysis indicated 85 mph) when the motorcycle struck a deer at Worden Ave. The motorcyclist was ejected and travelled approximately 350 ft from point of impact.			

Dangerous Behaviors

Speed	Failure to Yield	Impaired Driving	Disregard Traffic Control	Reckless / Careless Driving
X				

Other Behaviors of Note:

- Motorcycle

Enforcement Response

Concerns Identified	➤ Speed Enforcement
Near-Term Strategies (0-90 Days)	• Continued enforcement in the Jackson Safety Corridor
Mid-Term Strategies (90-365 days)	•
Long-Term Strategies (1 year +)	•

Engineering/Planning Response

Concerns Identified	➤ MDOT Jurisdiction ➤ Speed
Near-Term Strategies (0-3 years)	
Mid-Term Strategies (4-10 years)	•
Long-Term Strategies (11-20 years)	•

Education Response:

Concerns Identified	➤ Speeding ➤ Animal Collison
Near-Term Strategies	•
Mid-Term Strategies	•
Long-Term Strategies	•

90 Day Update

Due: Month Year

One Year Update

Due: Month Year

Notes