# **Contract Modification**

8/28/2017 4:34 PM

FieldManager 5.3a

Contract: \_2016-026, Nichols Arboretum Sewer and Siphon Rehabilitation

Cont. Mod. Revision Number Number		Cont. Mod. Electronic Date File Created		Net Change	Awarded Contract Amount		
1		8/28/2017	No	\$314,700.42	\$890,900.00		
Route		Managing Office City of Ann Arbor		<b>District</b> 0	Entered By Michael Nearing		
ontract Locat lichols Arboretu							

# **Short Description**

Change Order to add various items of extra work

# **Description of Changes**

This Change Order will add various items of extra work to the project that were necessary to properly complete the work in accordance with the plans and specifications due to site conditions that varied from those as shown on the plans.

#### Increases / Decreases

Item Description	Item Code	Prop. I	Proj. Line	Project	Catg. Item Type	Quantity Change Unit	Unit Price	Dollar Value
Clean 36-inch Dia. Sanitary Sewer	_210	0155 (	0155	_2016-026	001 Original	589.000 Lft	44.40000	\$26,151.60

Reason: During the course of the work it was discovered that MH 71-69254 was not located on the mainline 36" sanitary sewer. In order to perform the work of the contract, it was necessary to add the cleaning of the sanitary sewer from MH 71-69254 to MH 71-68806. Also during the work, it was discovered that this segment of sanitary sewer contained a great deal of medical waste and debris and needed to be removed from the sanitary sewer system in order to ensure proper flow and maximize system capacity. This length of sewer was 320.0 Lft.

During the course of the work, it was discovered that the segment of sanitary sewer from MH 71-69895 to 71-69896 was in poor condition and needed to be lined in order to preserve its integrity. This length of sewer was 269.0 Lft.

Removal and Replacement of Chamber Roof	_219	0200	0200	_2016-026	001	Original	-1.000 LS	6,276.00000	\$-6,276.00	
Reason: This item of work's description was incorrectly enterned into FieldManager when the contract was originally created. The item number 7127051 will be created to replace this item of work.										
CIPP Line 36-inch Dia Sanitary Sewer	220	0205	0205	_2016-026	001	Original	269.000 Lft	210.00000	\$56,490.00	
Reason: During the poor condition and	Reason: During the course of the work, it was discovered that the segment of sanitary sewer from MH 71-69895 to 71-69896 was in poor condition and needed to be lined in order to preserve its integrity. This length of sewer was 269.0 Lft.									
Maintenance Gravel	3060020	0045	0045	_2016-026	001	Original	-305.000 Ton	75.00000	\$-22,875.00	
Reason: This item of work was added to the contract in error and should be removed to maintain the integrity of the contract.										
							Total	Dollar Value:	\$53,490.60	

### **Contract Modification**

8/28/2017 4:34 PM

FieldManager 5.3a

#### New Items

Item Description	Item Code	Prop. Line		Project	Catg. ItemType	Proposed Quantity Unit	Unit Price	Dollar Value
Sewer Flow Control,	_8507060	0285	0285	_2016-026	001 Adjustment	32,608.700 Dlr	1.00000	\$32,608.70

Reason: During the course of the work, a differing site condition was discovered which the Contractor requested a 60 calendar day time extension in order to complete the work of the project to which the Engineer agreed. This item of work will compensate the Contractor for the additional time that the by-pass pumping system was on-site and available for use on the project. The adjustment is calculated as follows:

Adjustment = (additional duration of work/original contract duration) x original contract unit price

The original notice to proceed date was December 23, 2017; the original substantial completion date for the work was March 24, 2017. Original contract duration for the purposes of this work = 92 calendar days.

Therefore, the adjustment to the contract for Item of Work No. 209 is as follows:

Adjustment =  $(60/92) \times $50,000 = $32,608.70$ 

\_\_Vactor Rental, 1047060 0270 0270 \_\_2016-026 001 Extra 32,073.820 Dlr 1.00000 \$32,073.82 Complete

Reason: During the course of the work, it was discovered that a portion of the existing 10" sanitary sewer owned by the University of Michigan adjacent to our work site began to leak when the by-pass pumping system was put into place. As a result, it was necessary to employ the use of vactor trucks to intercept the leaking sewage effluent before it could enter the Huron River during the lining of the existing 36" sanitary sewer between MH 71-68806 and MH 71-70049. This item of work compensates the Contractor for the use of their vactor trucks and represents payment in full for all labor, material, equipment, and clean-up costs including the disposal of the effluent associated with the work.

Liquidated 1080000 0280 0280 \_2016-026 001 Adjustment 55,900.000 Dlr -1.00000 \$-55,900.00 Damages

Reason: The Contractor did not complete the necessary construction activities by the revised Substantial Completion date of May 23, 2017. Consequently, liquidated damages for the failure to complete the necessary work are being assessed as follows:

Original Substantial Completion date was March 24, 2017.

A sixty (60) calendar day time extension was recommended by the Engineer.

Revised Substantial Completion Date is now May 23, 2017.

The project's work was Substantially Completed on July 6, 2017.

43 calendar days of realized delay occurred between May 23rd and July 6, 2017.

Total Amount of Liquidated Damages is 43 calendar days @ \$1,350.00 per day = \$55,900.00.

Aggregate Base, 8 3020020 0230 0230 \_2016-026 001 Modified 305.000 Syd 75.00000 \$22,875.00

Reason: This item of work was inadvertently omitted from the original contract. We are adding it by this contract modification in order to properly perform the work of the project.

# **Contract Modification**

8/28/2017 4:34 PM

FieldManager 5.3a

#### New Items

Item Description	ltem Code	Prop. Line	Proj. Line	Project	Catg.	ItemType	Proposed Quantity		Unit Price	Dollar Value
_ 1" x 3" Aggregate,	3027011	0220	0220	_2016-026	001	Extra	134.00	) Syd	120.00000	\$16,080.00

Reason: This item of work is necessary to compensate the Contractor for additional trucking costs associated with excavating for, furnishing, placing, compacting, and hauling excavated soils associated with installing additional gravel access path located in the Amphitheather of the Nichols Arboretum. See the project files for supporting documentation regarding this item of work.

Reason: This item of work is necessary to compensate the Contractor for additional trucking costs associated with excavating for, furnishing, placing, compacting, and hauling excavated soils associated with installing additional gravel access path located in the Amphitheather of the Nichols Arboretum. See the file for additional documentation regarding this item of work and all our agreements with the Contractor for the prosecution of the work.

\_CIPP Line 36-inch 4027001 0235 0235 \_2016-026 001 Extra 455.000 Ft 279.00000 \$126,945.00 Dia. Sanitary
Sewer, MH
71-69257 to MH
71-68806,
Complete

Reason: It was discovered during the course of the work that MH 71-69254 was not located on the mainline 36" diameter sanitary sewer. This caused a need to re-define the construction sequence of the sewer rehabilitation and extended the limits of the work in order to have it properly performed. This item of work will compensate the Contractor in full for all additional labor, material, and equipment costs associated with CIPP lining this segment of sanitary sewer due to its depth. See the file for additional documentation regarding this item of work and all our agreements with the Contractor for the prosecution of the work.

\_\_Manned Entry of 4027050 0245 0245 \_\_2016-026 001 Extra 2.000 Ea 2,500.00000 \$5,000.00 Sanitary Sewer, w/Life-support Equipment, Complete

Reason: During the course of the work it was discovered that MH 71-69254 was not located on the mainline 36" sanitary sewer. Consequently, it was necessary to extend the limits of the work in order to be able to terminate the proposed sewer liner at an accessible manhole. This item of work will compensate the Contractor for all expenses associated with manned entry into the sanitary sewer with full life-support equipment in order to remove portions of the liner that would plug lateral connections to the mainline sewer. See the file for additional documentation regarding this item of work and all our agreements with the Contractor for the prosecution of the work.

\_ Sanitary Sewer, 4027050 0250 0250 \_2016-026 001 Extra 1.000 Ea 1,560.00000 \$1,560.00 Drop Connection,

Clean out, MH 71-70050, Complete

Reason: During the course of the work it was discovered that the external drop connection in sanitary manhole 71-70050 was plugged and not functioning. It is necessary to clean out this drop connection and restore it to working order to prevent future damage to the manhole. This unit price is payment in full for all labor, materials, and equipment to perform the work. See the file for additional documentation regarding this item of work and all our agreements with the Contractor for the prosecution of the work.

# **Contract Modification**

8/28/2017 4:34 PM

FieldManager 5.3a

#### **New Items**

Item Description	ltem Code	Prop. Line	Proj. Line	Project	Catg.	ItemType	Proposed Quantity Unit	Unit Price	Dollar Value
Custom Manhole, Cast-in-place, Special	4037050	0240	0240	_2016-026	001	Extra	1.000 Ea	50,416.30000	\$50,416.30

Reason: During the course of the work a sharp bend in the mainline 36" sanitary sewer was discovered between manholes 71-70047 and 71-70048. Upon discussions with City Staff and the Contractor, it was determined that a manhole needed to be constructed over this sharp bend and the bend in the sewer removed after the manhole has been constructed. This item of work includes all labor, materials, and equipment needed to construct this custom manhole and protect the surrounding work and environment. See the file for additional documentation regarding this item of work and all our agreements with the Contractor for the prosecution of the work.

\_ Furnish and Install 7127050 0265 0265 \_2016-026 001 Extra 1.000 Ea 1,995.00000 \$1,995.00 Hatch, Chamber 71-69893, Complete

Reason: This existing chamber currently is covered with a steel plate that cannot be secured. This item of work will compensate the contractor for all labor, material, and equipment costs associated with furnishing and installing a hatch that can be locked and prevent unintended entry. See the file for additional documentation regarding this item of work and all our agreements with the Contractor for the prosecution of the work.

Reason: During the course of the project's construction this chamber was cleaned in accordace with requirements of the plans and specifications. Upon cleaning the chamber, it was discovered that its condition was better than originally anticipated and it could be rehabilitated as part of this project. This item of work will compensate the Contractor for all labor, material, and equipment costs associated with rehabilitating this structure and applying a hydrogen sulfide resistant coating to protect it from further damage. See the file for additional documentation regarding this item of work and all our agreements with the Contractor for the prosecution of the work.

Reason: During the course of the project's construction this chamber was cleaned in accordnce with requirements of the plans and specifications. Upon cleaning the chamber, it was discovered that its condition was better than originally anticipated and it could be rehabilitated as part of this project. This item of work will compensate the Contractor for all labor, material, and equipment costs associated with rehabilitating this structure and applying a hydrogen sulfide resistant coating to protect it from further damage. See the file for additional documentation regarding this item of work and all our agreements with the Contractor for the prosecution of the work.

# **Contract Modification**

8/28/2017 4:34 PM

FieldManager 5.3a

### **New Items**

Item Description	Item Code	Prop. Line	Proj. Line	Project	Catg.	. ItemType	Proposed Quantity Unit	Unit Price	Dollar Value
_ Removal and Replacement of	7127051	0275	0275	_2016-026	001	Modified	1.000 LS	6,276.00000	\$6,276.00

Chamber Roof Slab - MH -71-69895

> Reason: This item of work's description was incorrectly enterned into FieldManager when the contract was originally created. The description of this item is the correct description as stated in the contract documents for the original item of work \_219.

> > Total Dollar Value: \$261,209.82

### **Time Extensions**

Site	Site Description	Site Type	Original Compl. Date/Days	Additional No. of Days	New Compl. Date/Days	
00	Overall Contract Site	Working Days	0	60	60	

Reason: During the course of the work it was discovered that MH 71-69254 was not on the mainfine 36" sanitary sewer. Consequently, it was necessary to re-define the process for lining the sanitary sewer due to this significant changed condition. It was also necessary to extend the limits of the work and add several new items of work to the project in order to properly complete the work of this project.

This extension of contract time will extend the Substantial Completion Date of the work to May 23, 2017.

The Final Completion Date for the project will be extended by sixty calendar days as well which in turn revises the Final Completion date to July 30, 2017.

All contract requirements remain in effect during the performance of the work of this contract.

### **Project / Category Summary**

Project/Catg	Project/Category Description	Federal Number	Project Status	Finance System	Control Section	Dollar Value
_2016-026	Nichols Arboretum Sewer and Siphon Rehabilitation	0	CNST			
001	Category					\$314,700.42
					Total:	\$314,700.42
			Total N	et Change Am	ount:	\$314,700.42

# **Contract Modification**

8/28/2017 4:34 PM

FieldManager 5.3a

If authorized, the contractor agrees to do the work outlined payment in full the basis of payment as indicated. Prime C to do the work described herein in accordance with the term	ontractor, you are authorized and ins	
Contractor: Liqui-Force Serivuces USA Inc.	Michael G. Nearing, P.E., Proje Michael G. Nearing, P.E.	<del>-</del>
Signature Da	signature Signature	Date
Nicholas Hutchinson, P.E., City Engineer	Craig Hupy, Public Services Are	ea Administrator
Signature Da	Signature	Date
Howard S. Lazarus, City Administrator		
Signature Da	nte	