## EXHIBIT B1 COMPENSATION

This exhibit further defines the Contingency Task

Task Description	Number	Amount
CONTINGENCY	6	
Well Abandonment and Replacement (W-70-92 and P-4D)	6.1	\$ 9,503.00
PFAS Sampling	6.2	\$ 6,199.48
Purge Well and MH-A Maintenance	6.3	\$ 10,898.00
	-	\$ 26,600.48

-