

CITY OF ANN ARBOR, MICHIGAN Community Services Area

Planning & Development Services Unit 301 E Huron St, Ann Arbor, MI 48107-8647 www.a2gov.org

Housing Board of Appeals Staff Report

Subject: BBA 14-0019

1614 South Blvd

Description and Discussion:

The owner of the residence located at 1614 South Blvd request a variance from the requirement for natural light and ventilation in the finished room in the cellar for use as a sleeping room. Natural light requires glazing area equal to 8% of the room's floor area and natural ventilation equal to 4% of that same area as required by section 8:502 (1) and (2).

The homeowner had the egress window installed in 2012 to create a bedroom after the initial housing inspection had cited the cellar as not habitable. Installation of an egress window is only one of the many requirements for a cellar bedroom.

I completed a cellar requirements worksheet, which is required by code for cellar occupancy. The proposed bedroom lacked adequate light and ventilation.

There are 2 windows in the intended bedroom. The new egress window glazing area measures 39" high by 21-1/2" wide or 5.8 square feet. The second window, (existing) has a glazing area that measures 27" by 13-1/2" or 2.5 square feet. Total glazing area is 8.3 square feet.

The room measures 11' by 16'or 176 square feet. The code requires natural light to equal 8% of the total floor area in this case 14 square feet. This falls short by 5.7 square feet. The code also requires natural ventilation equal to 4% of the total floor area, in this case, 7 square feet. The ventilation area of the egress window measures 21-1/2 "by 17-1/2" or 2.6 square feet. The second windows ventilation area measures 30" by 16-1/2" or 3.4 square feet, (this window at the time of the inspection did not have a screen or the hardware to open the window but per the owner has since been repaired to open and has a screen) Total ventilation area measures 6 square feet. This falls short by 1 square foot.

The house was built in 1968. There are 3 bedrooms on the first floor and one bath. At some time the cellar has been finished with 2 rooms and a bath. With no egress windows, the cellar has never been habitable.

Section 8:515 (2) of the Ann Arbor Housing Code:

The City of Ann Arbor Housing Code allows the Housing Board of Appeals to grant variances on existing structural elements of a building.

BBA 14-005



City of Ann Arbor

PLANNING & DEVELOPMENT SERVICES — CONSTRUCTION SERVICES

 Mailing:
 301 E. Huron St.
 P.O. Box 8647 ₁ Ann Arbor, Michigan 48107-8647

 p. 734.794.6263
 ↑ 734.994.8460 ∮ building@a2gov.org

APPLICATION FOR VARIANCE - BUILDING BOARD OF APPEALS

A second

Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested: ight and Ventilation Code is 8:502 and 8:503 Light 8% of area Short 5.7 sqft Ventilation 4% of area Short 1.0 sqft Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26	Address of Applicant: 3680 Highlander Way E. Ann Arbor, MI 48108 Daytime Phone(734) 276-6502 Fax:(734) 761-9221	
Daytime Phone. (734) 276-6502 Fax. (734) 761-9221 Email: _silvanagraf@comcast.net Applicant's Relationship to Property	Daytime Phone: (734) 276-6502 Fax: (734) 761-9221	
Daytime Phone: (734) 276-6502 Fax. (734) 761-9221 Email: _silvanagraf@comcast.net Applicant's Relationship to Property:	Daytime Phone. (734) 276-6502 Fax: (734) 761-9221	
Applicant's Relationship to Property: Vice-President of Trantor Inc. & Property Mana. Section 2: Property Information Address of Property: 1614 South Blvd Zoning Classification: Tax ID# (if known): Facel to 09-09-33-407-034 *Name of Property Owner Trantor Inc. *If different than applicant, a letter of authorization from the property owner must be provided. Section 3: Request Information 2 Variance Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested: light and Ventilation Code is 8:502 and 8:503 Light 8% of area short 5.7 sqft Ventilation 4% of area short 1.0 sqft Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26	Email: Silvanagraf@comcast.net	
Address of Property: 1614 South BIVd Zoning Classification: Tax ID# (if known): Pacal to 09-09-33-407-034 *Name of Property Owner Trantor Inc. *If different then applicant, a letter of authorization from the property owner must be provided. Section 3: Request Information 2 Variance Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested: light and Ventilation Code is 8:502 and 8:503 Light 8% of area Short 5.7 sqft Ventilation 4% of area Short 1.0 sqft Example: 2003 Building Code, Section 5:26		
Address of Property: 1614 South Blvd Zoning Classification: Tax ID# (if known): Pacel is 69-09-33-407-034 *Name of Property Owner Trantor Inc. *If different than applicant, a letter of authorization from the property owner must be provided. Section 3: Request Information Warriance Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested: light and Ventilation Code is 8:502 and 8:503 Light 8% of area Short 5.7 sqft Ventilation 4% of area Short 1.0 sqft Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26	Applicant's Relationship to Property: Vice-President of Trantor Inc. & Property Mar	nager
Zoning Classification: Tax ID# (if known): Pacal to cq-cq-33-407-034 *Name of Property Owner Trantor Inc. *If different than applicant, a letter of authorization from the property owner must be provided Section 3: Request Information Wariance Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested: Light and Ventilation Code is 8:502 and 8:503 Light 8% of area Short 5.7 sqft Ventilation 4% of area Short 1.0 sqft Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landin Section 5:26	Section 2: Property Information	intervisional and a second second second
Tax ID# (if known): Paced to G9-09-33-407-034 *Name of Property Owner Trantor Inc. *If different than applicant, a letter of authorization from the property owner must be provided. Section 3: Request Information Description: Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested: Light and Ventilation Code is 8:502 and 8:503 Light 8% of area Short 5.7 sqft Ventilation 4% of area Short 1.0 sqft Example: 2003 Building Code, Section 5:26 Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26	Address of Property: 1614 South Blvd	To the state of th
*Name of Property Owner Trantor Inc. *If different then applicant, a letter of authorization from the property owner must be provided. Section 3: Request Information Variance Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested: Light and Ventilation Code is 8:502 and 8:503 Light 8% of area Short 5.7 sqft Ventilation 4% of area short 1.0 sqft Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26	Zoning Classification:	
*Name of Property Owner Trantor Inc. *If different than applicant, a letter of authorization from the property owner must be provided. Section 3: Request Information Wariance Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested: Light and Ventilation Code is 8:502 and 8:503 Light 8% of area Short 5.7 sqft Ventilation 4% of area Short 1.0 sqft Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26		
Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested: Light and Ventilation Code is 8:502 and 8:503 Light 8% of area Short 5.7 sqft Ventilation 4% of area Short 1.0 sqft Example: 2003 Building Code, Section 5:26 Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26	*Name of Property Owner Trantor Inc.	ed
Chapter(s) and Section(s) from REQUIRED dimension: PROPOSED dimension: which a variance is requested: Light and Ventilation Code is 8:502 and 8:503 Light 8% of area Short 5.7 sqft Ventilation 4% of area Short 1.0 sqft Example: 2003 Building Code, Section 5:26 Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26	Section 3: Request Information	Part of all survey of many of the survey of
which a variance is requested: ight and Ventilation Code is 8:502 and 8:503 Light 8% of area short 5.7 sqft Ventilation 4% of area short 1.0 sqft Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26	☑ Variance	The Mills and English of Mills and Mills and Anthropic and
Light 8% of area short 5.7 sqft Ventilation 4% of area short 1.0 sqft Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landii Section 5:26		n:
Ventilation 4% of area short 1.0 sqft Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26	ight and Ventilation Code is 8:502 and 8:503	
Example: 2003 Building Code, Example: 7' Ceiling Clearance Example: 6'5" under landing Section 5:26	Light 8% of area short 5.7 sqft	mateur freid de februarieur man de februarieur en arc'h 1 e
Section 5:26	Ventilation 4% of area short 1.0 sqft	***************************************
		nding
Give a detailed description of the work you would need the variance for (attach additional chapts if neces		
	Give a detailed description of the work you would need this variance for (attach additional sheets if need	cessary)
I need to leave the house the way it is now	I need to leave the house the way it is now	programme in partie above a magnetic

Section 4: Variance Request	
The City of Ann Arbor Building Board of Appeals has the powers granted by State law and Building Codes. A variance may be granted by the Building Board of Appeals only in cases involving practical difficulties or unnecessary hardships when ALL of the following is found TRUE.	
Please provide a complete response to each item below. These responses, together with the required materials in Section 5 of this application, will form the basis for evaluation of the request by staff and the Building Board of Appeals.	
Are there hardships or practical difficulties to complying with the Code? Are these hardships or practical difficulties an exception or unique to the home compared to other homes in the City?	
The additional window (2x3 sqft) that would need to be opened in the cellar at 1614 South to comply with	
involves cutting a piece of the cement driveway to create a window well, opening a hole in a brick wall at	
the basement wall. The weight of that side of the house rests on that side (supporting beams run perpen	ıdicular).
Are the hardships or practical difficulties more than mere inconvenience or inability to obtain a higher financial return, or both? (explain) Both	
The weight of that side of the house rests on that side (supporting beams run perpendicular). There is alr	eady an
egress window (new \$3,300) and a small additional window. Opening another window may open possibil	ities of
water problems and structural problems that are non-existent now. The cost of this is aproximately \$ 000).
3. What effect will granting the variance have on the neighboring properties?	
It will make the house desirable to nice quiet families and add value to the neighborhood . In the	
past this house had 2 illegal bedrooms in the basement crowded with as many as 12 people with no egres	SS.
4. What physical characteristics of your property in terms of size, shape, location or topography prevent you from using it in a way that is consistent with the Code? This house is a ranch. There is no room to add a fourth bedroom on the first level We already invested \$3,300 to open a safe Egress Window for the purpose of creating an official	
bedroom in the basement	
5. Is the condition which prevents you from complying with the ordinance self-imposed? How did the condition come about?	
We intended to create a legal bedroom in the basement and hired a professional "Emergency Egress"	
He acted like hemew the code and proceeded to execute the project. I clearly told the owner of the comp	any
that the purpose of the investment was a "legal" bedroom. He claimed to have ample experience with the	city.
Section 5: Required Materials	,
The following materials are required for all variance requests. Failure to provide these materials will result in an incomplete application and will delay staff review and Building Board of Appeals consideration of the request. The materials listed below must accompany the application and constitute an inseparable part of the application. All materials must be provided on 8 ½" by 11" sheets. If incomplete, you will be scheduled for the NEXT MEETING DATE ON THE FOLLOWING MONTH.	
☐ State proposed use of property, size of lot and size and type of proposed changes.	
☐ Building floor plans showing interior rooms, including dimensions, (continued)	
☐ Photographs of the property and any existing buildings involved in the request	
☐ Any other graphic or written materials that support the request.	
☐ Letter of Authority if being represented by someone other than the property owner.	

Section 6: Acknowledgement	
SIGNATURES MUST BE SIGNE	D IN PRESENCE OF NOTARY PUBLIC
	ove named Chapter(s) and Section(s) of the Applicable ode and/or 2006 Michigan Building Code for the stated ad hereto.
(734) 276-6502	Alvare m
Phone Number	Signature
silvanagraf@comcast.net	Silvana Graf / Trantor Inc.
Email Address	Print Name
contained in the materials submitted herewith are dates, deadlines and instructions. Applicant ack	of the aforementioned statements, and the statements true and correct and have received all coversheets with nowledges that they are aware of these meeting dates g dates and times. All applicants are expected to know present their appeal in a timely fashion. Signature
the Building Board of Appeals permission to acce variance request. As a condition of granting an	g and Development Services unit staff and members of ess the subject property for the purpose of reviewing my ny variance, the property owner is also responsible for nits to inspect and final out any outstanding work at this
named applicant and made oath that he/she ha and knows the contents thereof, and that the sam	2014 before me personally appeared the above is read the foregoing application by him/her subscribed the is true as to his/her own knowledge except as to those and belief as to those matters, he/she believes them to Notary Public Signature DICHNE J. CUTTY Print Name
	FUSE ONLY #250 00
BBA Action:	
OUSTANDING PERMITS:	



CITY OF ANN ARBOR

100 N. FIFTH AVE - ANN ARBOR. MI 48104 (734) 794-6267

Receipt Number: 2015-00002600

Project Number

BBA14-005

Receipt Print Date

07/11/2014

Address

1614 SOUTH BLVD

Applicant

TRANTOR, INC

Owner

TRANTOR, INC

Project Description

FEES PAID

0026-033-3370-0000-4361 P&D - APPEAL FEES 13/14

BBA 1 & 2 FAMILY

0026-033-3370-0000-4361

250.00

Total Fees for Account 0026-033-3370-0000-4361:

250.00

TOTAL FEES PAID

250.00

DATE PAID Friday, July 11, 2014 PAID BY: LOGOS

PAYMENT METHOD: CREDIT CARD TYPE NOT

To. Building Board of Appeals of the City of Ann Arbor.

279 of July, 2014

Qear Sirs

I hereby authorize Silvana Graf to represent Trantor Inc and myself, Paul Flavio Graf, the President and owner of Trantor Inc which in turn owns 1614 South Bivd, to act on my behalf during the process of Application for Variance in front of the Building Board of Appeals of the City of Ann Arbor and any other necessary procedures related to my properties belonging to Trantor Inc.

Thank you very much, best regards.

Paul Flavio Graf

PAGE 1



CITY OF ANN ARBOR, MICHIGAN
Community Services Area
Planning & Development Services Unit
100 North Fifth Avenue, P.O. Box 8647,
Ann Arbor, Michigan 48107-8647
Phone: (734) 994-2674
Fax: (734) 994-2798
www.a2gov.org

CELLAR REQUIREMENTS WOORKSHEET 8:503 (6)

	DATE ADDRESS	Inspector
	IS THERE:	
	A) 8% light and 4% ventilation for each habitable room?	YES NO
	Where?	
	B) Required light and ventilation openings are above grade	YES NO
	or have window wells?	YES NO
	C) An escape window?	YES NO
N/	(A D) Second Means of Egress (Multiple Family ONLY)?	YES NO
	E) Stairway(s) to grade/grade floor to code (8:504 a, b)?	X YES NO
	F) Weatherproof and draft tight space?	YES NO
	G) Dry and mold/mildew free?	YES NO
	H) R-11 insulation in exterior walls?	NOUNKNOWN
	If unknown, is 60 degrees maintained per code?	YES NO
	I) adequate heat (return air, if forced hot air)?	× YES NO
	J) A Continuous, finished ceiling?	YES NO
	K) Electrical outlets to building code?	X YES NO
	L) Smoke detectors per code?	YES NO
	M) Ceilings: 6'8" for 80% of the habitable space: balance not less than 6'0"?	X YES NO
	N) Door/opening to habitable space a minimum 6'2" in height and 22" in width	
) One-hour separation of unit from gas/oil fired heating/water heating applian	ces serving other units? Boiler/AC
		YES NO
	P) Floor and exterior walls waterproofed as necessary?	YES NO
N	AQ) Inside stairs have rated enclosure at grade (multiple family only)?	YES NO
NECO CORY	B) Regularly cleaned sanitary sewer? YES - Date of last cleaning	12/19/12 NO REVED LA
,	S) Proof of past flooding (within 5 years) or present dampness?	YES X NO 6/15/16
NED CONT	(7) Radon testing? YES - Date of last test ; result;	NO REVICE 1/16/19
,	Grade Measurement - Floor to average outside ground level	
	Existing 5 8" Required 3 4"	ET WATE
	Location of main electrical panel? CELLAY.	
	Easy access to panel for all occupants of all units?	X YES NO
		The state of the s

LIGHT AND VENTILATION MEASUREMENTS FOR BASEMENT

SQ FT 11' X 16' = 176 SQ FT 🗐

 $X 8\% = 14 (light) \times 4\% = 7 (ventilation)$

<u>- 8.3</u> <u>-2.6</u>

Short 5.7 short 4.4

VENT 21 ½" X 17 ½" = 2.6 SQ FT

<u>LIGHT</u> 39" X 21 ½" = 5.8 SQ FT ∮

5.8 + 2.5 = 8.3


VENT 30" X 161/2" = 3.4 SQ FT small window needs screens & hardware to count

Emergency Egress LLC 450 E. Square Lake Road - Trey, Michigan 48085

450 E. Square Lake Road - Troy, Michigan 48085 Phone: (248) 879-0671

Name:





NINDOW:

Proposal Submitted To:

We propose to:	12" BOST WES
Install egress window(s) 28" x 46"	' 31" x 41" Other
Security Screen Trim interi	or with wood
Install Bowman Kemp white meta	l window well Natural Stone well
Install Wellcraft polyethylene wind	dow well Other
Install drain to be tied to drain tile	mike Femenzeny en greggen
Trim exterior of window with flashing	The Frances KN9 CT.
Pea/pebble rock at base of well	
Eighteen (18) month warranty on labo	
Lifetime warranty on window	en e
Repair any irrigation due to excavation	n e e e e e e e e e e e e e e e e e e e
Other	

Payment to be made as follows:

ACCEPTED. The above prices, specifications and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made as outlined above.


By


By

Note: This proposal by be withdrawn by us if not accepted within days.













CITY OF ANN ARBOR

Planning & Development Services

Mailing Address: 301 E. Huron Street, PO Box 8647

Ann Arbor, MI 48107-8647

Phone – (734) 794-6264 Fax – (734) 994-8460

rentalhousing@a2gov.org

For Inspections Results go to: www.a2gov.org/permits Select "Permits"

HOUSING INSPECTION CODE VIOLATION NOTICE initial Inspection Date Apt# Reinspection Date/Time YOU HAVE THE RIGHT TO APPEAL VIOLATIONS OR DEADLINES TO THE BOARD OF APPEALS The following code violations have been cited during this inspection. Fleen m:55 7 CUTIS -8

Omission of reference to any item during this inspection shall not nullify any requirement of the housing code nor exempt the owner/agent from meeting such requirements.

Your signature confirms that you have read and understand all violations and notes cited on this document. If you cannot read the handwriting or do not understand why a violation was cited, please discuss this with the inspector before signing this form.

Inspector Signature/Date		Authorized Agent Signature/Date	are constructing and an area deposition on the house follows and the construction of t	
White-Office / Yellow-1 st / Pink-Init	ial		Page	_of_Z



CITY OF ANN ARBOR

Planning & Development Services

Mailing Address: 301 E. Huron Street, PO Box 8647

Ann Arbor, MI 48107-8647

Phone – (734) 794-6264 Fax – (734) 994-8460

rentalhousing@a2gov.org

For Inspections Results

For Inspections Results go to: www.a2gov.org/permits Select "Permits"

	HOUSIN	IG INSPECTION	V CODE VIOLATIO	ON NOTICE	
Address 6/4 S	auth	BIVO	Apt #	Initial Inspection Da	4/27/12
Reinspection Date/Time	***************************************				

following	code violations have been cited during this inspection.
A. Colombia (Colombia)	180 Rosn #2-
	REPAIR CASTMENT WIMPAUS T OPERATE
and the state of t	PROPERLY + INSTAll MISS HAWD/ES 8509
Seasonateles	BED/Com #3
	REPAIR CASEMENT WINDOW TO UPENATE
	PROPELY - REPIAL BROKEN WINDER PRO
	8:509
	REPLACE 18A7764 12 STOKE ALASH- 852)
	BATH
	MAND 15 2) SINK SHUT-UFF3-850)
-	ECURE TOILET REPAIR RUL- au - 8507
	REG ZE TOR PEELL OFF-8509
	CON BACKSPIASH TO CONTENTUR-8509
**********************	Exteriar-
	STRVICE ENTRANCE CAISE IS IN DISPORTAN
	HNE A ICEUSED ELECTRICIAN REPLACE THE
	S.E. CABIE - PERMIT RECOURTS - 8505
	SCRAPE + PAINT WINDOWS INSIDE + CUT- 8509
	REGIAZE WINDOWS - 8502
	INSTALL VACUUM BREAKERS OF ALL HESE BIRS-8
	INSTALL CAFEL IN EFTERING 77/E73-8505
	Mellan SUMP MISCHARGE -8509
	Omission of reference to any item during this inspection shall not nullify any requirement

Your signature confirms that you have read and understand all violations and notes cited on this document. If you cannot read the handwriting or do not understand why a violation was cited, please discuss this with the inspector before signing this form.

Inspector Signature/Date)a	Authorized Agent Signature/Date/	XIM X July
inspector signature/bate			
White-Office / Yellow-1 st / Pink-Init	tial		Page of



& D Radon Tech

Radon Test Results Report

Client: TRANTOR INC

Client Address:

City: Phone:

State: 1/ F 28"

Zæ

Test Address:

1614 SOUTH BLVD

Average radon level during the test

City: ANN ARBOR

MI Zio: State:

0.5 pC/4

Test Device Location: FINISHED LOWER LEVEL BEDROOM WITH EGRESS

Unit Serial # CRM510 2025

WINDOW

Weather Conditions: COLD 20 -35F.

Start time: 1:50PM 1.16.13

Stop time: 1:00PM 1.18.13

PURPOSE OF THIS INSPECTION REPORT

To provide a professional opinion of a structure's radon levels at the time of the test period, limited to the conditions identified in this report.

EPA EXPLANATION OF TEST RESULTS

Radon is the second leading cause of lung cancer, after smoking. The U.S. Environmental Protection Agency (EPA) and the Surgeon General strongly recommend taking further action when the home's radon test results are 4.0 pCi/l (picocuries per liter of air) or greater. Radon levels less than 4.0 pCi/l still pose some risk and in many cases may be reduced. The national average indoor radon level is about 1.3 pCi/l while outdoor radon levels average 0.4 pCi/l. The higher a home's radon level, the greater the health risk to you and your family. Smokers and former smokers are at especially high risk. EPA recommends that you use an EPA or State-approved contractor trained to fix radon problems You can call your state radon office to obtain information, including a list of EPA or State-approved radon contractors who can fix or can help you develop a plan for fixing the radon problem. Many questions you may have can be found in EPA's publication "Home Buyer's and Seller's Guide to Radon".

LIMITATIONS OF LIABILITY

D & D Radon Tech cannot guarantee the necessary conditions were maintained during the test period. There can be uncertainty with any radon measurement due to statistical variations and other factors such as changes in the weather and operation of the dwelling. While our agents and we make every effort to maintain the highest possible quality control and include checks and verification steps in our procedures, we make NO WARRANTY OF ANY KIND, EXPRESSED OR IMPLIED, for the consequences of erroneous test results. D & D Radon Tech nor its employees or agents shall not be liable under any claim, charge or demand, whether in contract, tort, or otherwise, for any and all loss, cost, charge, claim, demand, fee, or expense of any nature or kind arising out of, connected with, resulting from, or sustained as a result of any radon test.

RADON TEST DATA


This test was performed with a femto-TECH CRM-510, an EPA and Industry approved testing device. The test was performed in accordance with the current Standards and Guidelines accepted for radon testing.

Test Technician: Daniel Heilmann

D & D Radon Tech 1552 Barrington PL Ann Arbor, MI 48103 Mobile: 734.255.0427

Email accurateradon@aol.com

License/Certification number: NEHA NRPP ID 100219RT




4

22×18: (27×14: 3v+ 1 xcs)

40% neut - 14


Z

C &



1st Floor

BACKYARD



Basement