

Authority: 1949 PA 300, Sec.257.622
Compliance: Required MSP UD-10E
Penalty: \$100 and/or 90 days (Rev 11/2020)

External # 1315687
Crash ID 2739967

Page 01 of 01
File Class 9300-1

STATE OF MICHIGAN TRAFFIC CRASH REPORT

ORI MI 8121800
Department Name Ann Arbor Police Department
Incident # 220043422
Reviewer KANDT (38400)

Crash Date 11/02/2022
Crash Time 19:05
No. of Units 02
Crash Type Single Motor Vehicle
Special Circumstances None Fleeting Police Hit and Run Unknown School Bus Animal
Special Checks Fatal Non-Traffic Area ORV/Snowmobile

County 81 - Washtenaw
Traffic Control Signal
Relation to Roadway On the Road
Weather Clear
Area INTR Within Intersection

City/Twp 89 - Ann Arbor
Contributing Circumstances 1st None 2nd
Light Dark-Lighted
Road Surface Condition Dry
Total Lanes 02
Speed Limit 25
Posted No

Work Zone (if applicable) Type Workers Present Activity Location

Prefix Primary Road Name Brockman
Road Type BLVD
Suffix Divided Roadway

Distance / Direction 40 Feet S
Trafficway Not Physically Divided

Prefix E
Intersecting Road Name Stadium
Road Type BLVD
Suffix Divided Roadway

Unit Number 01
Unit Known Yes
State MI
Driver License Number #####
Date of Birth (Age) ##/##/#### (82)
License Type Operator Chauffeur Moped
Endorsements Cycle Farm Recreation
Sex M Race W
Total Occupants 01
Hazardous Action Unknown

Unit Type MV
Driver Information #####
ANN ARBOR, MI 48104-4710 (###) ###-####
Driver is Owner Yes Injury O
Position Front - Left
Restraint Shoulder and Lap Belt

Driver Condition at Time of Crash 1st Appeared Normal 2nd
Driver Distracted By Not Distracted
Ejected Trapped
Airbag Deployed Not Deployed

Hospital NONE
Ambulance NONE

Alcohol Suspected No
Contributing Factor No
Alcohol Test Type Breath Blood Urine Field PBT Refused Not Offered
Alcohol Test Results Pending Test Results:
Interlock Device No

Drug Suspected No
Contributing Factor No
Drug Test Type Blood Urine Field Refused Not Offered
Drug Test Results Pending Test Results:
Citation Issued Hazardous Other

Vehicle Registration DKP2568
State MI
Vehicle Description Year 2016 Make HONDA Model CIVIC Color BLACK

VIN 2HGFC2F76GH505436
Vehicle Type Passenger Car, SUV, Van
Special Vehicles Not Applicable
Private Trailer Type
Vehicle Defect

Automation System(s) in Vehicle No
Automation System Level in Vehicle No Automation
Automation System Level Engaged at Time of Crash No Automation

Insurance Company #####
Insurance Policy # #####
Towed By Towed To

Location of Greatest Damage 07
First Impact 07
Extent of Damage (Power Unit and/or Trailers) Minor Damage
Vehicle Direction S
Vehicle Use Private
Action Prior Turning Left

Sequence of Events First 16 - Bicyclist
Second Third Fourth
(● indicates MOST harmful event)

Passenger Information
Date of Birth (Age) Sex Race Position
Injury Ejected Trapped Airbag Deployed

Hospital
Ambulance

Passenger Information
Date of Birth (Age) Sex Race Position
Injury Ejected Trapped Airbag Deployed

Hospital
Ambulance

Carrier Information
USDOT MC MPSC
Driver's CDL Type Endorsements H P T N S X
CDL Exempt Farm Other

GVWR/GCWR 10,000 lbs. or Less 10,001 - 26,000 lbs. Greater than 26,000 lbs.
Vehicle Configuration Cargo Body Type Medical Card Hazardous Material Placard Cargo Spill ID # Class #

Owner Information
Owner Information

Damaged Property Public Owner & Phone

SANITIZED

SANITIZED SANITIZED SANITIZED SANITIZED SANITIZED SANITIZED SANITIZED

| | | | | | | | | | | | |
|---|---|---|---|---|--|---|---|-----------------------|---|------------------------------------|--|
| Unit Number 02 | Unit Known Yes | State CA | Driver License Number ##### | Date of Birth (Age) ###/##/#### (25) | License Type <input type="radio"/> Operator <input type="radio"/> Chauffeur <input type="radio"/> Moped | Endorsements <input type="radio"/> Cycle <input type="radio"/> Farm <input type="radio"/> Recreation | Sex F | Race W | Total Occupants 01 | Hazardous Action Unknown | |
| Unit Type B | Driver Information ##### ANN ARBOR, MI 48104 (###) ###-#### | | | Driver is Owner No | Injury A | Position Bicyclist | Restraint Helmet Worn | | | | |
| Driver Condition at Time of Crash <small>1st</small> 2nd | | | | Driver Distracted By Not Distracted | | | Ejected | Trapped | Airbag Deployed Not Equipped | | |
| Hospital UNIV OF MICHIGAN HEALTH SYSTEM | | | | | Ambulance HURON VALLEY AMB INC | | | | | | |
| Alcohol Suspected No | Contributing Factor No | Alcohol Test Type <input type="radio"/> Breath <input type="radio"/> Blood <input type="radio"/> Urine <input type="radio"/> Field <input type="radio"/> PBT <input type="radio"/> Refused <input checked="" type="radio"/> Not Offered | | | Alcohol Test Results <input type="radio"/> Pending | Test Results: | Interlock Device No | | | | |
| Drug Suspected No | Contributing Factor No | Drug Test Type <input type="radio"/> Blood <input type="radio"/> Urine <input type="radio"/> Field <input type="radio"/> Refused <input checked="" type="radio"/> Not Offered | | | Drug Test Results <input type="radio"/> Pending | Test Results: | Citation Issued <input type="radio"/> Hazardous <input type="radio"/> Other | | | | |
| Vehicle Registration | State | Vehicle Description DIAMONDBACK | Year | Make | Model | Color BLACK | | | | | |
| VIN | Vehicle Type | | Special Vehicles Not Applicable | | Private Trailer Type | Vehicle Defect | | | | | |
| Automation System(s) in Vehicle No | Automation System Level in Vehicle No Automation | | | | Automation System Level Engaged at Time of Crash No Automation | | | | | | |
| Insurance Company ##### | | | Insurance Policy # ##### | | | Towed By | | Towed To | | | |
| Location of Greatest Damage 11 | First Impact 11 | Extent of Damage (Power Unit and/or Trailers) No Damage | | | Vehicle Direction W | Vehicle Use | | | Action Prior Crossing at Intersection | | |
| Sequence of Events <small>● indicates MOST harmful event</small> | | <small>First</small> 17 - Motor Veh in Transport | | <small>Second</small> 45 - Other Fixed Object | | <small>Third</small> | | <small>Fourth</small> | | | |

| | | | | | | | | | | |
|------------|-----------------------|--|---------|-----------|---------------------|-----|------|----------|-----------|--|
| PASSENGERS | Passenger Information | | | | Date of Birth (Age) | Sex | Race | Position | Restraint | |
| | Injury | | Ejected | Trapped | Airbag Deployed | | | | | |
| Hospital | | | | Ambulance | | | | | | |
| PASSENGERS | Passenger Information | | | | Date of Birth (Age) | Sex | Race | Position | Restraint | |
| | Injury | | Ejected | Trapped | Airbag Deployed | | | | | |
| Hospital | | | | Ambulance | | | | | | |

| | | | | | | | | | | |
|--|-----------------------|--|--|-----------------|--------------|---|------|------|---------|--|
| TRUCK/BUS | Carrier Information | | | | USDOT | MC | MPSC | | | |
| | Driver's CDL Type | | Endorsements <input type="radio"/> H <input type="radio"/> P <input type="radio"/> T <input type="radio"/> N <input type="radio"/> S <input type="radio"/> X | | | CDL Exempt <input type="radio"/> Farm <input type="radio"/> Other | | | | |
| GVWR/GCWR <input type="radio"/> 10,000 lbs. or Less <input type="radio"/> 10,001 - 26,000 lbs. <input type="radio"/> Greater than 26,000 lbs. | Vehicle Configuration | | | Cargo Body Type | Medical Card | Hazardous Material <input type="radio"/> Placard <input type="radio"/> Cargo Spill | | ID # | Class # | |

| | | | | | | | | | | |
|--------|-------------------|--|--|--|-------------------|--|--|--|--|--|
| OWNERS | Owner Information | | | | Owner Information | | | | | |
| | | | | | | | | | | |

| | | | | | | | | | | |
|---------|---------------------|--|--|--|---------------------|--|--|--|--|--|
| WITNESS | Witness Information | | | | Witness Information | | | | | |
| | | | | | | | | | | |

| | | | | |
|-------------------------------------|---|---|-------------------------------|---------------------|
| Investigated at Scene Yes | Reported Date (Time) 11/02/2022 (19:05) | 1st Investigator Name (Badge) MURDOCK (030) | 2nd Investigator Name (Badge) | Photos No |
|-------------------------------------|---|---|-------------------------------|---------------------|

Narrative

THE DRIVER OF UNIT 1 SAID HE WAS TURNING LEFT FROM GOING WESTBOUND ON E STADIUM AVE TO SOUTHBOUND ON BROCKMAN BLVD. HE HAD A FLASHING YELLOW TRAFFIC SIGNAL, THERE WAS NO ONCOMING TRAFFIC, AND HE DID NOT SEE ANYONE IN THE CROSSWALK. THE EAST/WEST CROSSWALK DID HAVE A WALK SIGNAL. AS HE TURNED SOUTH HE SAID HE SAW A BICYCLE APPROACHING FROM HIS LEFT AND HE STOPPED HIS VEHICLE. THE DRIVER SAID HE THEN SAW THE CYCLIST TUMBLE TO THE GROUND IN FRONT OF HIM. NEW DAMAGE NEAR THE FRONT LEFT WHEEL SHOWED WHERE THE BIKE HIT THE SIDE OF THE CAR. THE CYCLIST SAID THE CAR WAS STILL IN MOTION WHEN SHE STRUCK IT. THE BIKE, A BLACK DIAMONDBACK ROAD BIKE WITH NO LIGHTS, SEEMED TO HAVE SCRATCHES BUT NO SIGNIFICANT DAMAGE. THE CYCLIST WAS TRANSPORTED TO U OF M HOSPITAL BY HVA FOR INJURIES TO HER FACE. THE CYCLIST SAID SHE THOUGHT HER FACE STRUCK THE PAVEMENT AFTER GOING ACROSS THE HOOD OF THE CAR. I OBSERVED MINOR SCRATCHES ON HER HELMET.

